

| Vendor | Model | Vendor:DeviceID | Drivers | Supported CPU | Notes |
|-----------|--------------------------|-----------------|------------|-----------------------------|--|
| Acer Labs | M5229 | 10b9: 5229 | devb-eide | X86 | rev 0x19-0xC1 UDMA 2 |
| Acer Labs | ThunderX | 0x0402:0x5621 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB IDE Disk |
| Acer Labs | M5229 | 10b9: 5229 | devb-eide | X86 | rev 0xC2-0xC3 UDMA 4 |
| Acer Labs | M5229 | 10b9: 5229 | devb-eide | X86 | rev 0xC4 UDMA 5 |
| Acer Labs | M5287 | 10b9: 5287 | devb-eide | X86 | SATA |
| Acer Labs | M5289 | 10b9: 5289 | devb-eide | X86 | SATA |
| ACOM | FlashKey | 0x0c0b:0xb001 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive |
| Adaptec | AHA-1510 A | N/A | devb-aha2 | X86 | PIO ISA SCSI host adapter without BIOS |
| Adaptec | AHA-1520 A | N/A | devb-aha2 | X86 | PIO ISA SCSI host adapter |
| Adaptec | AHA-1522 A | N/A | devb-aha2 | X86 | PIO ISA SCSI host adapter with floppy controller |
| Adaptec | AHA-1522 B | N/A | devb-aha2 | X86 | PIO ISA SCSI host adapter |
| Adaptec | AHA-1530 P | N/A | devb-aha2 | X86 | PIO ISA-to- Fast SCSI host adapter |
| Adaptec | AHA-1540 A | N/A | devb-aha4 | X86 | Bus master ISA SCSI host adapter. |
| Adaptec | AHA-1540 B | N/A | devb-aha4 | X86 | Bus master ISA SCSI host adapter. |
| Adaptec | AHA-1540 C | N/A | devb-aha4 | X86 | Bus master ISA SCSI host adapter. |
| Adaptec | AHA-1540 CF | N/A | devb-aha4 | X86 | Bus master ISA-to-Fast SCSI host adapter. |
| Adaptec | AHA-1542 A | N/A | devb-aha4 | X86 | Bus master ISA SCSI host adapter with floppy controller. |
| Adaptec | AHA-1542 B | N/A | devb-aha4 | X86 | Bus master ISA SCSI host adapter with floppy controller. |
| Adaptec | AHA-1542 C | N/A | devb-aha4 | X86 | Bus master ISA SCSI |

| | | | | | | |
|---------|-------------|------------|-----------|----------------|---|--|
| | | | | | host adapter with floppy controller. | |
| Adaptec | AHA-1542 CF | N/A | devb-aha4 | X86 | Bus master ISA-to-Fast SCSI host adapter with floppy controller | |
| Adaptec | AHA-2740 | N/A | devb-aha7 | X86 | Bus master EISA-to-Fast SCSI host adapterx09 | |
| Adaptec | AHA-2740 T | N/A | devb-aha7 | X86 | TwinChannel Bus master EISA-to-Fast SCSI host adapter | |
| Adaptec | AHA-2740 W | N/A | devb-aha7 | X86 | Bus master EISA-to-Fast and Wide SCSI host adapter | |
| Adaptec | AHA-2742 | N/A | devb-aha7 | X86 | Bus master EISA-to-Fast SCSI host adapter with floppy controller | |
| Adaptec | AHA-2742 T | N/A | devb-aha7 | X86 | TwinChannel Bus master EISA-to-Fast SCSI host adapter with floppy controller | |
| Adaptec | AHA-2742 W | N/A | devb-aha7 | X86 | Bus master EISA-to-Fast and Wide SCSI host adapter with floppy controller | |
| Adaptec | AHA-2840 A | N/A | devb-aha7 | X86 | Bus master VL-to-Fast SCSI host adapter | |
| Adaptec | AHA-2842 A | N/A | devb-aha7 | X86 | Bus master VL-to-Fast SCSI host adapter with floppy controller | |
| Adaptec | AHA-2902 E | 9004: 5078 | devb-aha8 | MIPS, PPC, X86 | PCI-to-Fast SCSI (non-bootable, | |

| | | | | | | |
|---------|-----------------|------------------|-----------|----------------|--|--|
| | | | | | external) . No Support for MIPS BE | |
| Adaptec | AHA-2902 I | 9004: 5078 | devb-aha8 | MIPS, PPC, X86 | PCI-to-Fast SCSI (non-bootable, internal) . No Support for MIPS BE | |
| Adaptec | AHA-2904 | 9004: 5078 | devb-aha8 | MIPS, PPC, X86 | PCI-to-Fast SCSI (non-bootable) | |
| Adaptec | AHA-2910 | 9004: 5078 | devb-aha8 | MIPS, PPC, X86 | PCI-to-Fast SCSI (non-bootable) . No Support for MIPS BE | |
| Adaptec | AHA-29160 | 9005: 0080 | devb-aha8 | MIPS, PPC, X86 | PCI-to-Ultra160 SCSI. No Support for MIPS BE | |
| Adaptec | AHA-2930CV | 9004: 3868, 3869 | devb-aha8 | MIPS, PPC, X86 | No Support for MIPS BE | |
| Adaptec | AHA-2930 U | 9004: 3860 | devb-aha8 | MIPS, PPC, X86 | PCI-to-Ultra Fast SCSI. No Support for MIPS BE | |
| Adaptec | AHA-2930 UW | 9004: 8878, 7888 | devb-aha8 | MIPS, PPC, X86 | PCI-to-Ultra Wide Fast SCSI. No Support for MIPS BE | |
| Adaptec | AHA-2940 | 9004: 7178 | devb-aha8 | MIPS, PPC, X86 | Bus master PCI-to-Fast SCSI host adapter. No Support for MIPS BE | |
| Adaptec | AHA-2940 AU | 9004: 6178 | devb-aha8 | MIPS, PPC, X86 | Bus master PCI-to-Fast SCSI host adapter. No Support for MIPS BE | |
| Adaptec | AHA-2940 U | 9004: 8178 | devb-aha8 | MIPS, PPC, X86 | PCI-to-Ultra Single-ended SCSI. No Support for MIPS BE | |
| Adaptec | AHA-2940 U Dual | N/A | devb-aha8 | MIPS, PPC, X86 | Dual Channel PCI-to-Ultra Wide Internal Single-ended SCSI with 50- | |

| | | | | | | |
|---------|------------------|----------------|-----------|----------------|--|--|
| | | | | | pin external connector. No Support for MIPS BE | |
| Adaptec | AHA-2940 UW | 0x9004: 0x8178 | devb-aha8 | MIPS, PPC, X86 | PCI-to-Ultra Wide Single-ended SCSI. No Support for MIPS BE | |
| Adaptec | AHA-2940 UW Dual | N/A | devb-aha8 | MIPS, PPC, X86 | Dual Channel PCI-to-Ultra Wide Internal Single-ended SCSI with Wide external connector. No Support for MIPS BE | |
| Adaptec | AHA-2940 W | 9004: 7178 | devb-aha8 | MIPS, PPC, X86 | Bus master PCI-to-Fast and Wide SCSI host adapter. No Support for MIPS BE | |
| Adaptec | AHA-2944 | 0x9004: 0x7478 | devb-aha8 | MIPS, PPC, X86 | PCI-to-Fast Differential SCSI. No Support for MIPS BE | |
| Adaptec | AHA-2944 UW | 9004: 8478 | devb-aha8 | MIPS, PPC, X86 | PCI-to-Ultra Wide Differential SCSI. No Support for MIPS BE | |
| Adaptec | AHA-2944 W | N/A | devb-aha8 | MIPS, PPC, X86 | PCI-to-Fast and Wide Differential SCSI. No Support for MIPS BE | |
| Adaptec | AHA-3940 | 0x9004: 0x7278 | devb-aha8 | MIPS, PPC, X86 | Bus master PCI-to-Fast SCSI host adapter. No Support for MIPS BE | |
| Adaptec | AHA-3940 AU | N/A | devb-aha8 | MIPS, PPC, X86 | MultiChannel PCI-to-Ultra SCSI. No Support for MIPS BE | |
| Adaptec | AHA-3940 AUW | N/A | devb-aha8 | MIPS, PPC, X86 | MultiChannel PCI-to-Ultra | |

| | | | | | |
|---------|------------------|-------------------|-----------|-------------------|--|
| | | | | | Wide SCSI. No Support for MIPS BE |
| Adaptec | AHA-3940 AUWD | N/A | devb-aha8 | MIPS, PPC, X86 | MultiChannel PCI-to-Ultra Wide SCSI with dual external connectors. No Support for MIPS BE |
| Adaptec | AHA-3940 U | 0x9004: 0x8278 | devb-aha8 | MIPS, PPC, X86 | MultiChannel PCI-to-Ultra SCSI |
| Adaptec | AHA-3940U2x | 0x9005: 0x0050 | devb-aha8 | MIPS, PPC, X86 | Ultra2 SCSI Adapter. No Support for MIPS BE |
| Adaptec | AHA-3940 UW | 9004: 8278 | devb-aha8 | MIPS, PPC, X86 | Bus master PCI-to-Fast and Wide SCSI host adapter. No Support for MIPS BE |
| Adaptec | AHA-3940 UWD | 9004: 8278 | devb-aha8 | MIPS, PPC, X86 | MultiChannel PCI-to-Ultra Wide SCSI with Dual external connectors. No Support for MIPS BE |
| Adaptec | AHA-3940 W | 9004: 7278 | devb-aha8 | MIPS, PPC, X86 | Bus master PCI-to-Fast and Wide SCSI host adapter. No Support for MIPS BE |
| Adaptec | AHA-3944 | 0x9004: 0x7578 | devb-aha8 | MIPS, PPC, X86 | MultiChannel PCI-to- Differential SCSI host adapter. No Support for MIPS BE |
| Adaptec | AHA-3944 U | 0x9004: 0x8578 | devb-aha8 | MIPS, PPC, X86 | Fast-Wide/ Ultra-Wide Differential SCSI host adapter. No Support for MIPS BE |
| Adaptec | AHA-3944 W | 0x9004: 0x7578 | devb-aha8 | MIPS, PPC, X86 | MultiChannel PCI-to-Wide |

| | | | | | | |
|---------|---------------|------------------------------|-----------|----------------|--|--|
| | | | | | Differential SCSI. No Support for MIPS BE | |
| Adaptec | AHA-3944 AUWD | N/A | devb-aha8 | MIPS, PPC, X86 | No Support for MIPS BE | |
| Adaptec | AHA-3944 UWD | 9004: 8578 | devb-aha8 | MIPS, PPC, X86 | MultiChannel PCI-to-Ultra Wide Differential SCSI with Dual external connectors. No Support for MIPS BE | |
| Adaptec | AHA-3950U2x | 0x9005: 0x0050, 0x0051 | devb-aha8 | MIPS, PPC, X86 | Ultra2 SCSI Adapter. No Support for MIPS BE | |
| Adaptec | AHA-4944 UW | 0x9004: 0x7678, 0x8678 | devb-aha8 | MIPS, PPC, X86 | Quad Channel PCI-to-Ultra and Wide Differential SCSI. No Support for MIPS BE | |
| Adaptec | AHA-4944 W | 9004: 7678 | devb-aha8 | MIPS, PPC, X86 | Quad Channel PCI-to-Fast and Wide Differential SCSI | |
| Adaptec | AIC-6260 | N/A | devb-aha2 | X86 | PIO single chip SCSI host adapter. | |
| Adaptec | AIC-6360 | N/A | devb-aha2 | X86 | PIO single chip SCSI host adapter. | |
| Adaptec | AIC-755X | 9004: 5075 | devb-aha8 | MIPS, PPC, X86 | | |
| Adaptec | AIC-7560 | 0x9004: 0x6075 | devb-aha8 | MIPS, PPC, X86 | | |
| Adaptec | AIC-7770 | N/A | devb-aha7 | X86 | Bus master single chip SCSI host adapter. | |
| Adaptec | AIC-7850P | 0x9004: 0x5078 | devb-aha8 | MIPS, PPC, X86 | Bus master single chip PCI-SCSI host adapter. No Support for MIPS BE | |
| Adaptec | AIC-7855 | 9004: 5578 | devb-aha8 | MIPS, PPC, X86 | Single-chip PCI-to-Fast SCSI. No | |

| | | | | | | |
|---------|------------|---|--------------|----------------|---|--|
| | | | | | Support for MIPS BE | |
| Adaptec | AIC-7856 | 9004: 5678 | devb-aha8 | MIPS, PPC, X86 | Single-chip PCI-to-Fast SCSI. No Support for MIPS BE | |
| Adaptec | AIC-7860 | 0x9004: 0x6078, 0x7860, 0x6278 | devb-aha8 | MIPS, PPC, X86 | PCI SCSI Controller. No Support for MIPS BE | |
| Adaptec | AIC-7861 | 0x9004: 0x6178 | devb-aha8 | MIPS, PPC, X86 | PCI SCSI Controller. No Support for MIPS BE | |
| Adaptec | AIC-785X | | devb-adpu360 | MIPS, PPC, X86 | SCSI Ctrlr. No Support for MIPS BE | |
| Adaptec | AIC-7870 | 0x9004: 0x7078, 0x6778 | devb-aha8 | MIPS, PPC, X86 | Bus master single chip PCI-SCSI host adapter. No Support for MIPS BE | |
| Adaptec | AIC-787X | 0x9004: 0x7778 | devb-aha8 | MIPS, PPC, X86 | PCI SCSI Controller. Support for this controller is also found in the devb-adpu360 driver. | |
| Adaptec | AIC-7880 | 0x9004: 0x8078 | devb-aha8 | MIPS, PPC, X86 | Integrated bus master single chip PCI Ultra Wide SCSI host adapter | |
| Adaptec | AIC-7883 U | 9004: 8378 | devb-aha8 | MIPS, PPC, X86 | Ultra-Wide SCSI host adapter. No Support for MIPS BE | |
| Adaptec | AIC-788X | 0x9004: 0x8778 | devb-aha8 | MIPS, PPC, X86 | Ultra-Wide SCSI host adapter. Support for this controller is also found in the devb-adpu360 driver. | |
| Adaptec | AIC-7890 | 9004: 7890, 001F | devb-aha8 | MIPS, PPC, X86 | Ultra 2 SCSI host adapter. | |

| | | | | | |
|---------|------------|--|--------------|-------------------|--|
| | | | | | No Support for MIPS BE |
| Adaptec | AIC-7890AB | 0x9005: 0x0010 | devb-aha8 | MIPS, PPC, X86 | Ultra-Wide SCSI host adapter. No Support for MIPS BE |
| Adaptec | AIC-7891 | 9005: 001F | devb-aha8 | MIPS, PPC, X86 | 64Bit PCI Ultra2 SCSI host adapter. No Support for MIPS BE |
| Adaptec | AIC-7895 | 0x9004: 0x7895 | devb-aha8 | MIPS, PPC, X86 | Single-chip PCI-to- MultiChannel Ultra Wide SCSI. No Support for MIPS BE |
| Adaptec | AIC-7896 | 9005: 005F | devb-aha8 | MIPS, PPC, X86 | Ultra2 SCSI Controller. No Support for MIPS BE |
| Adaptec | AIC-7897 | 9005: 005F | devb-aha8 | MIPS, PPC, X86 | Ultra2 SCSI Controller. No Support for MIPS BE |
| Adaptec | AIC-7899 | 0x9004: 0x7891, 0x7892, 0x7893, 0x7894, 0x7896, 0x7897. 0x9005: 0x0020, 0x0030, 0x002F, 0x003F, 0x00CF | devb-aha8 | MIPS, PPC, X86 | Ultra2-Wide SCSI host adapter. No Support for MIPS BE |
| Adaptec | AMM-1570 | N/A | devb-aha2 | X86 | PIO ISA-to-Fast SCSI host adapter |
| Adaptec | AIC-7901 | 0x9005; 0x801E | devb-adpu320 | MIPS, PPC, X86 | Single-Channel PCI-X to Ultra320 SCSI Controller |
| Adaptec | AIC-7902 | 0x9005; 0x801F | devb-adpu320 | MIPS, PPC, X86 | Dual-Channel PCI-X to Ultra320 SCSI |
| Adaptec | 29320A-R | 0x9005; 0x8000 | devb-adpu320 | MIPS, PPC, X86 | 64-bit 133 MHz PCI-X, single-channel |

| | | | | | | |
|-------------------|------------------|--|------------|-----------------------------|--|--|
| | | | | | Ultra320 SCSI card | |
| Adaptec | AIC-786X | 0x9004: 0x6478, 0x6578, 0x6678 | devb-aha8 | MIPS, PPC, X86 | SCSI Ctrlr. Support for this chipset is also found in the devb-adpu360 driver. | |
| Adaptec | AIC-789X | 0x9005; 0x8778, 0x0020, 0x0030, 0x003F, 0x001F, 0x002F, 0x0060, 0x0070, 0x005F, 0x006F, 0x007F, 0x008F, 0x009F, 0x00AF, 0x00BF, 0x0080, 0x0090, 0x00A0, 0x00B0, 0x00DF, 0x00EF, 0x00FF, 0x00FF, 0x00D0, 0x00E0, 0x00F0 | devb-aha8 | MIPS, PPC, X86 | Ultra-Wide SCSI host adapter. Support for this controller is also found in the devb- adpu360 driver. | |
| Adaptec | AHA-2930U | 0x9004: 0x3860 | devb-aha8 | MIPS, PPC, X86 | AIC-2930U Ultra SCSI | |
| Adaptec | AHA-2940/2940W | 0x9004: 0x7178 | devb-aha8 | MIPS, PPC, X86 | | |
| Adaptec | AHA-4944W/4944U | 0x9004: 0x7678, 0x3B78, 0xEC78 | devb-aha8 | MIPS, PPC, X86 | | |
| Adaptec | AHA-2944UW | 0x9004: 0x8478 | devb-aha8 | MIPS, PPC, X86 | | |
| Adaptec | AIC-7888 | 0x9004: 0x8878 | devb-aha8 | MIPS, PPC, X86 | | |
| Adaptec | AIC-7892B | 0x9005: 0x0081 | devb-aha8 | MIPS, PPC, X86 | | |
| Adaptec | AIC-7899A | 0x9005: 0x00C0 | devb-aha8 | MIPS, PPC, X86 | | |
| Alcor Micro Corp. | Acer Flash drive | 0x58f:0x9382 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |

| | | | | | | |
|------------------------------------|---|---------------|------------|--------------------------|--|--|
| Algorithmics | P-5064 | N/A | devf-p5064 | MIPS | Flash filesystem support for the MIPS QED evaluation board. No Support for MIPS BE | |
| AMD | AM-53C974 | 1022: 2020 | devb-amd | MIPS, X86 | Bus master PCI-to-Fast SCSI host adapter. No Support for MIPS BE | |
| AMD | AM-79C974 KC | N/A | devb-amd | MIPS, X86 | Bus master PCI-to-Fast SCSI host adapter. No Support for MIPS BE | |
| AMD | PCB-756 | 1022: 7409 | devb-eide | X86 | UDMA 4 (untested) | |
| AMD | PCB-766 | 1022: 7411 | devb-eide | X86 | UDMA 5 (untested) | |
| AMD | PCB-768 | 1022: 7441 | devb-eide | X86 | UDMA 5 | |
| Apacer Technology, Inc. | Handy Steno 2.0 (256MB) | 0x1005:0xb113 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Apacer Technology, Inc. | 1G flash key (Handy HA202) | 0x1005:0xb113 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash key | |
| Apacer Technology, Inc. | Handy Steno HT202 | 0x1005:0xb113 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Apple | 30GB iPod Photo | 0x05ac:0x1209 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB iPod | |
| Apple | iPod MP3 Player | 0x05ac:0x1300 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB iPod | |
| ATI | IXP-150/200/250 | 0x1002:0x4349 | devb-eide | X86 | UDMA 5 | |
| Buffallo | 11in1 CardReader/Writer | 0x0411:0x0058 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB Card Reader | |
| BusLogic/ Mylex | BT-440C | N/A | devb-btmm | X86 | Bus master VL SCSI host adapter. | |
| BusLogic/ Mylex | BT-445C | N/A | devb-btmm | X86 | Bus master VL SCSI host adapter with floppy controller. | |
| BusLogic/ Mylex | BT-542B | N/A | devb-btmm | X86 | Bus master ISA SCSI | |

| | | | | | | |
|--------------------------------|---------------------------------|---------------|------------|--------------------------|--|--|
| | | | | | host adapter with floppy controller. | |
| BusLogic/Mylex | BT-542D | N/A | devb-btmm | X86 | Bus master ISA-to-Fast SCSI host adapter with floppy controller. | |
| BusLogic/Mylex | BT-545C | N/A | devb-btmm | X86 | Bus master ISA SCSI host adapter with floppy controller. | |
| BusLogic/Mylex | BT-545S | N/A | devb-btmm | X86 | Bus master ISA-to-Fast SCSI host adapter with floppy controller. | |
| BusLogic/Mylex | BT-646S | N/A | devb-btmm | X86 | Bus master MCA SCSI host adapter. | |
| BusLogic/Mylex | BT-747S | N/A | devb-btmm | X86 | Bus master EISA SCSI host adapter. | |
| BusLogic/Mylex | BT-946C | 4B10: 1040 | devb-btmm | X86 | Bus master PCI-to-Fast SCSI host adapter with floppy controller. | |
| Canon | Powershot A70 (CF card) | 0x04a9:0x30b5 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB camera | |
| CMD | CMD-646 | 1095: 0646 | devb-eide | X86 | UDMA 33 | |
| CMD | CMD-648 | 1095: 0648 | devb-eide | X86 | UDMA 33, UDMA 66 | |
| CMD | CMD-649 | 1095: 0649 | devb-eide | X86 | UDMA 33, UDMA 66, UDMA 100 | |
| Comstar | Comstar 32M flash disk | 0x090a:0x14c1 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Corsair | Flash Voyager (1G) | 0x067b:0x2517 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Creative Labs | Soundblaster 16 SCSI | N/A | devb-aha2 | X86 | PIO ISA SCSI host adapter | |
| Creative Labs | MuVo MP3 Player | 0x041e:0x4120 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB MP3 player | |
| Cypress | Cypress hard drive | 0x04b4:0x6830 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB hard drive | |
| Cyrix | Cx5530 | 1078: 0102 | devb-eide | X86 | UDMA 33 | |
| Dura Micro | DMI SA2 | 0x0c0b:0xb001 | devu-mass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |

| | | | | | | |
|--------------------------------|---|---------------|--------------|--------------------------|--|--|
| Flash | CFI NOR Flash | N/A | devf-generic | ARM, MIPS, PPC, SH4, X86 | Support all standard CFI Nor Flash parts | |
| Geek Squad | Geek Squad 1.0 GB and Memory Traveldrive | 0x08ec:0x0016 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| GemLight | UPD720130 (USB IDE Disk) | 0x14c2:0x0001 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB IDE Disk | |
| Generic | IDE/EIDE/ATAPI | N/A | devb-eide | X86 | Supports most EIDE interfaces. | |
| Generic | Generic 16M flash key | 0x1043:0x8006 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Generic | Generic 128M flash key and Transcend JetFlash | 0x058f:0x9380 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Generic | Generic USB Flash Part | 0x0ef5:0x2202 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Generic | FlashKey | 0x0d7d:0x0100 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Generic | USB Mass Storage Devices | n/a | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB Mass storage Devices compliant with Mass Storage Specifications Overview (Rev 1.2), Bulk Only (Rev 1.0), CBI Specification (Rev 1.1), UFI Command Specification (Rev 1.0) (see http://www.usb.org/developers/devclass_docs) | |
| Hewlett-Packard | PhotoSmart 945 Digital Camera | 0x03f0:0x4002 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB camera | |
| HighPoint Tech | HPT-366 | 1103: 0004 | devb-eide | X86 | rev 0x01 UDMA 4 (untested) | |
| HighPoint Tech | HPT-370 | 1103: 0004 | devb-eide | X86 | rev 0x3+ UDMA 5 | |
| HighPoint Tech | HPT-372 | 1103: 0005 | devb-eide | X86 | UDMA 6 | |
| HighPoint Tech | HPT-374 | 1103: 0008 | devb-eide | X86 | UDMA 6 | |

| | | | | | | |
|---------|--------------------|----------------|------------|--------------------------|-----------------------------------|--|
| Hyundai | 2.2 Gig Flash Disk | 0x0ea0:0x2136 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB Flash Drive | |
| IBM | CD-ROM | 0x04b3:0x4427 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB CD-ROM | |
| Intel | 82371FB (PIIX) | 8086: 1230 | devb-eide | ARM, MIPS, PPC, SH4, X86 | BIOS Mode transfers | |
| Intel | 82371SB (PIIX3) | 8086: 7010 | devb-eide | ARM, MIPS, PPC, SH4, X86 | MDMA 2 | |
| Intel | 82371AB (PIIX4) | 8086: 7111 | devb-eide | PPC, X86 | | |
| Intel | 82801AA (ICH) | 8086: 2411 | devb-eide | ARM, MIPS, PPC, SH4, X86 | UDMA 4 | |
| Intel | 82801AB (ICH0) | 8086: 2421 | devb-eide | ARM, MIPS, PPC, SH4, X86 | UDMA 4 | |
| Intel | 82801BA (ICH2) | 8086: 244A | devb-eide | ARM, MIPS, PPC, SH4, X86 | UDMA 5 | |
| Intel | 82801BAM (ICH2-M) | 8086: 244B | devb-eide | ARM, MIPS, PPC, SH4, X86 | UDMA 5 | |
| Intel | 82801CA (ICH3-S) | 8086: 248B | devb-eide | ARM, MIPS, PPC, SH4, X86 | UDMA 5 | |
| Intel | 82801CAM (ICH3-M) | 8086: 248A | devb-eide | ARM, MIPS, PPC, SH4, X86 | UDMA 5 | |
| Intel | 82801DB (ICH4) | 8086: 24CB | devb-eide | ARM, MIPS, PPC, SH4, X86 | UDMA 5 | |
| Intel | 82801EB (ICH5) | 0x8086: 0x24D1 | devb-eide | X86 | SATA. (released in 6.3.0 SP3) | |
| Intel | 82801EB (ICH5) | 0x8086: 0x24DB | devb-eide | X86 | UDMA 5 (released in 6.3.0 SP3) | |
| Intel | 82801ER (ICH5R) | 0x8086: 0x24DF | devb-eide | PPC, X86 | SATA. (released in 6.3.0 SP3) | |
| Intel | 82801FB (ICH6) | 0x8086: 0x2651 | devb-eide | PPC, X86 | SATA. (released in 6.3.0 SP3) | |
| Intel | 82801FR (ICH6R) | 0x8086: 0x2652 | devb-eide | PPC, X86 | SATA. (released in 6.3.0 SP3) | |
| Intel | 82801FB (ICH6) | 0x8086: 0x266F | devb-eide | PPC, X86 | UDMA 5 (released in 6.3.0 SP3) | |
| Intel | 82801FBM (ICH6M) | 0x8086: 0x2653 | devb-eide | PPC, X86 | SATA (released in 6.3.0 SP3) | |
| Intel | 82801GB (ICH7) | 0x8086: 0x27DF | devb-eide | PPC, X86 | UDMA 5 (released in 6.3.0 SP3) | |
| Intel | 82801GB (ICH7) | 0x8086: 0x27C0 | devb-eide | PPC, X86 | SATA (released in 6.3.0 SP3) | |

| | | | | | | |
|----------|--|-------------------|------------|-----------------------------|-------------------------------------|--|
| Intel | 82801GB (ICH7) | 0x8086: 0x27C4 | devb-eide | PPC, X86 | SATA (released in 6.3.0 SP3) | |
| Intel | 6300ESB (ICH) | 0x8086: 0x25A2 | devb-eide | X86 | UDMA 5 (release in 6.3.0 SP3) | |
| Intel | 6300ESB (ICH) | 0x8086: 0x25A3 | devb-eide | X86 | SATA (release in 6.3.0 SP3) | |
| Intel | 82801FB (ICH6) | 0x8086: 0x2651 | devb-ahci | PPC, X86 | SATA (released in 6.3.0 SP3) | |
| Intel | 82801FBM (ICH6M) | 0x8086: 0x2653 | devb-ahci | PPC, X86 | SATA (released in 6.3.0 SP3) | |
| Intel | 82801GB (ICH7) | 0x8086: 0x27c1 | devb-ahci | PPC, X86 | SATA (released in 6.3.0 SP3) | |
| Intel | 82801GBM (ICH7M) | 0x8086: 0x27c5 | devb-ahci | PPC, X86 | SATA (released in 6.3.0 SP3) | |
| Iomega | ZIP100 | 0x059b:0x0001 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB zip drive | |
| Iomega | ZIP250 | 0x059b:0x0030 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB zip drive | |
| Iomega | ZIP750 | 0x059b:0x0035 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB zip drive | |
| Iomega | Zip Drive 100M | 0x059b:0x0001 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB zip drive | |
| Kingston | USB Drive | 0x04e8:0x0100 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Kingston | Data Traveler 2.0, 1G | 0x0930:0x653d | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Kingston | Data Traveler Elite, 1G | 0x08ec:0x0015 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Kingston | DiskOnKey 1G | 0x08ec:0x0012 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Kingston | DiskOnKey 256M | 0x0951:0x1600 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Lacie | External Harddrive | 0x059f:0x0321 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB hard drive | |
| Lexar | JumpDrive Pro | 0x05dc:0xa400 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Lexar | JumpDrive Trio | 0x05dc:0xb013 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Lexar | Lexar flash drive | 0x0781:0x0810 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB compact flash | |
| Lexar | Jumpdrive (64M) | 0x05dc:0x0080 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Lexar | MP3 Player 512 external flash card | 0x05dc:0x4d40 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB MP3 player | |
| Lexar | Jumpdrive | 0x05dc:0xa400 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |

| | | | | | | |
|------------------------|--|---------------|-------------|--------------------------|---|--|
| Lyra | MP3 Player | 0x069b:0x070c | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB MP3 player | |
| M-Systems | DiskonKey | 0x8ec:0x10 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| M-Systems | DiskonKey V2 | 0x8ec:0x11 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| M-Systems | DiskGo | 0x8ec:0x12 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| M-Systems | DiskOnKey 16MB and 64MB | 0x08ec:0x0010 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drives | |
| M-Systems | 64M DiskOnKey | 0x08ec:0x0011 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| M-Systems | 9 in 1 Accelerate Card Reader | 0x05e3:0x0760 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB card reader | |
| Marvell | 88SX5080 | 0x11ab:0x5080 | devb-mvSata | X86 | SATA (released in 6.3.0 SP3) | |
| Marvell | 88SX5081 | 0x11ab:0x5081 | devb-mvSata | X86 | SATA (released in 6.3.0 SP3) | |
| Marvell | 88SX5040 | 0x11ab:0x5040 | devb-mvSata | X86 | SATA (released in 6.3.0 SP3) | |
| Marvell | 88SX5041 | 0x11ab:0x5041 | devb-mvSata | X86 | SATA (released in 6.3.0 SP3) | |
| Maxtor | 3000LE hard drive | 0x0d49:0x3010 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB hard drive | |
| Mobil | Mobil Disk Z4 (512M) and GXT (1G, 2G) | 0x126f:0x0161 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| National Semiconductor | CS-5530 | 0x100B: N/A | devb-eide | ARM, MIPS, PPC, SH4, X86 | | |
| NCR/Symbios | NCR-53c810 | N/A | devb-ncr8 | X86 | Bus master PCI-to-Fast SCSI host adapter. | |
| NCR/Symbios | NCR-53C810A | N/A | devb-ncr8 | X86 | Bus master PCI-to-Fast SCSI host adapter. | |
| NCR/Symbios | NCR-53c815 | N/A | devb-ncr8 | X86 | Bus master PCI-to-Fast SCSI host adapter. | |
| NCR/Symbios | NCR-53c820 | N/A | devb-ncr8 | X86 | Bus master PCI-to-Fast SCSI host adapter. | |
| NCR/Symbios | NCR-53c825 | N/A | devb-ncr8 | X86 | Bus master PCI-to-Fast | |

| | | | | | | |
|---------------------|-----------------------------------|------------------|------------|--------------------------|---|--|
| | | | | | SCSI host adapter. | |
| NCR/Symbios | NCR-53c860 | N/A | devb-ncr8 | X86 | Bus master PCI-to-Fast SCSI host adapter. | |
| NCR/Symbios | NCR-53c875 | N/A | devb-ncr8 | X86 | Bus master PCI-to-Fast SCSI host adapter. | |
| NCR/Symbios | NCR-53c885 | N/A | devb-ncr8 | X86 | Bus master PCI-to-Fast SCSI host adapter | |
| NCR/Symbios | NCR-53c895 | N/A | devb-ncr8 | X86 | Bus master PCI-to-Fast SCSI host adapter. | |
| NCR/Symbios | NCR-53c895A | 0x1000:0x0012 | devb-ncr8 | X86 | PCI to Ultra2 SCSI Controller | |
| NCR/Symbios | NCR-53c896 | N/A | devb-ncr8 | X86 | Bus master PCI-to-Fast SCSI host adapter. | |
| Nexdisk | Nexdisk PSD 56(128M) | 0x09a6:0x8001 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Nikon | Nikon Digital Camera E5700 | 0x04b0:0x0010 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB Camera | |
| Nikon | Digital Camera | 0x04b0:0x010C | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB Camera | |
| Nikon | Coolpix 8800VH | 0x04b0:0x0127 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB camera | |
| nVidia | nForce MCP | 0x10DE:0x01bc | devb-eide | X86 | UDMA 5 (untested) | |
| Olympus | D-510 Zoom Digital Camera | 0x07b4:0x0105 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB Camera | |
| Ours Technology Inc | OTI-6803 Solid Flash Disk | 0x0ea0:0x6803 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Panasonic | Panasonic DMC FZ10 Digital Camera | 0x04da:0x2372 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB camera | |
| PC Tech | RZ1000 | 1042: 1000, 1001 | devb-eide | X86 | PCI EIDE Controller | |
| Phison | Phison USB Disk Pro | 0x0d7d:0x1320 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB disk | |
| Pine | PT-CW320A CD-ROM | 0x04a5:0x6006 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB CD-ROM | |
| PNY | PNY Attache 1G | 0x0930:0x6534 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| PNY | PNY Attache 512M | 0x0930:0x6533 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |

| | | | | | | |
|-------------------------------------|--------------------------------------|---------------|------------|--------------------------|--------------------------------------|--|
| Prolific Technology Inc. | USB flash | 0x067b:0x2517 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Promise | PDC-20262 | 105A: 4D38 | devb-eide | X86 | UDMA 4 | |
| Promise | PDC-20267 | 105A: 0x4D30 | devb-eide | X86 | UDMA 4 | |
| Promise | PDC-20265 | 105A: 0D30 | devb-eide | X86 | UDMA 5 | |
| Promise | PDC-20269 | 105A: 4D69 | devb-eide | X86 | UDMA 5 | |
| RAM | Ram Disk | N/A | devb-ram | ARM, MIPS, PPC, SH4, X86 | Ram filesystem using block interface | |
| RAM | Ram Disk | N/A | devf-ram | ARM, MIPS, PPC, SH4, X86 | Ram filesystem using flash interface | |
| Samsung | MP3 Player | 0x04e8:0x5026 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB MP3 player | |
| SanDisk Corporation | Cruzer Micro | 0x0781:0x7112 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| SanDisk Corporation | Cruzer Micro | 0x0781:0x5151 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| SanDisk Corporation | Cruzer Mini 512MB & 1GB | 0x0781:0x5150 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| SanDisk Corporation | Cruzer Mini | 0x0781:0x7103 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| SanDisk Corporation | Cruzer (128M) | 0x0781:0x8888 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| ScanLogic | SL11R (USB IDE Disk) | 0x04ce:0x0002 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB hard drive | |
| SCM Microsystems (Shuttle) | E-USB ATA Bridge (Flash Card Reader) | 0x04e6:0x0001 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB card reader | |
| SCM Microsystems (Shuttle) | CF Multi-card reader | 0x04e6:0x0311 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB card reader | |
| SCM Microsystems (Shuttle) | ORCA Multi-card reader | 0x04e6:0x0325 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB card reader | |
| ServerWorks | CSB5 | 1166: 0212 | devb-eide | X86 | UDMA 4 (untested) | |
| ServerWorks | OSB4 | 1166: 0211 | devb-eide | X86 | UDMA 2 | |
| ServerWorks | CSB5 | 1166: 0212 | devb-eide | X86 | Revision 0x92+ UDMA 5 | |
| SIS | SiS-5513 | 0x1039:0x5513 | devb-eide | X86 | rev 0xD0 UDMA 2/4 | |
| SIS | SiS-5517 | 0x1039:0x5517 | devb-eide | X86 | UDMA 6 | |
| SIS | SiS-5518 | 0x1039:0x5518 | devb-eide | X86 | UDMA 6 | |
| SIS | SiS-180 | 0x1039:0x0180 | devb-eide | X86 | SATA | |
| SIS | SiS-181 | 0x1039:0x0181 | devb-eide | X86 | SATA | |
| SMI (Silicon Motion) | DiskOnKey | 0x090c:0x1000 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Sony | Sony USB Floppy Drive | 0x054c:0x002c | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB Floppy Drive | |

| | | | | | | |
|---------------------|--|---------------|------------|--------------------------|-----------------|--|
| Sony | Sony DSC-S30/S70/S75/F505V/F505/FD92 Cybershot/Mavica Digital Camera | 0x054c:0x0010 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB camera | |
| Sony | Sony HandyCam Memory Stick Reader | 0x054c:0x002e | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB card reader | |
| Sony | Micro Vault 256M Flash Key | 0x054c:0x0243 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Sony | Digital Camera | 0x054c:0x0010 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB Camera | |
| Sony | Camcorder | 0x054c:0x002e | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB camcorder | |
| Sony | DiskOnKey | 0x019e | devb-umass | ARM, MIPS, PPC, SH4, X86 | | |
| Sony | Floppy Disk Drive | 0x002c | devb-umass | ARM, MIPS, PPC, SH4, X86 | | |
| Spire | Spire USB 2.0 256MB & OCZ 1GB Rally | 0x0457:0x151 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| ST Microelectronics | STPC Consumer-II | 0x104A:0x021B | devb-eide | ARM, MIPS, PPC, SH4, X86 | | |
| Staples | Staples Relay 256MB | 0x0781:0x5202 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Staples | Smartdisk Firelite 60G | 0x0917:0x0207 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB hard drive | |
| SVDO | SVDO HVM-3 | | devb-eide | ARM, MIPS, PPC, SH4, X86 | | |
| Teac | CD-ROM | 0x0644:0x1000 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB CD-ROM | |
| Texas Instruments | OMAP 5905 | 0x104C: N/A | devb-eide | ARM, MIPS, PPC, SH4, X86 | | |
| Tone | Tone 5G 1 Inch Drive | 0x0ea0:0x2118 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB microdrive | |
| Transcend | TSJFlash | 0x058f:0x9380 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Transcend | TSJFlashA | 0x0c76:0x0005 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Trek | FlashKey | 0x0a16:0x9780 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| USB | Store n Go Pro 1GB | 0x08ec:0x0015 | devb-umass | ARM, MIPS, SH4, X86 | USB Flash Disk | |
| Vantec | Win NexStar 3 Port. Hard drive | 0x04b4:0x6830 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB hard drive | |
| Vantec | NexStar 2 IDE to USB @ | 0x0402:0x5621 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB hard drive | |

| | | | | | | |
|----------|-----------------------------------|---------------|------------|--------------------------|---|--|
| | Generic IDE to USB container | | | | | |
| Vantec | 7 in 1 card reader | 0x0402:0x5635 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB card reader | |
| Vantec | External disk enclosure NST 300UF | 0x067b:0x3507 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB disk drive | |
| Venturer | MP3 Digital Audio Player | 0x0419:0xa002 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB MP3 player | |
| VIA | 82C586B | 0x1106:0x0571 | devb-eide | X86 | 82686B PCI-ISA Bridge ver 0x40+ UDMA 5 | |
| VIA | 82C686B | 0x1106:0x0571 | devb-eide | ARM, MIPS, PPC, SH4, X86 | 8231 Bridge Chipset, UDMA 5 (untested) | |
| VIA | 82C686B | 0x1106:0x0571 | devb-eide | ARM, MIPS, PPC, SH4, X86 | 8233 Bridge Chipset, UDMA 5 (untested) | |
| VIA | 82C686B | 0x1106:0x0571 | devb-eide | ARM, MIPS, PPC, SH4, X86 | 8233C Bridge Chipset, UDMA 5 (untested) | |
| VIA | 82C686B | 0x1106:0x0571 | devb-eide | ARM, MIPS, PPC, SH4, X86 | 8233A Bridge Chipset, UDMA 6 | |
| VIA | 82C686B | 0x1106:0x0571 | devb-eide | ARM, MIPS, PPC, SH4, X86 | 8235A Bridge Chipset, UDMA 6 (untested) | |
| VIA | 82C686B | 0x1106:0x0571 | devb-eide | ARM, MIPS, PPC, SH4, X86 | 8237 Bridge Chipset, UDMA 6 (untested) | |
| VIA | 82C686B | 0x1106:0x0571 | devb-eide | ARM, MIPS, PPC, SH4, X86 | rev 0x6+, UDMA 2 | |
| VIA | VT8237 | 0x1106:0x3149 | devb-eide | ARM, MIPS, PPC, SH4, X86 | SATA | |
| Winbond | W83C553F | 0x10ad:0x0105 | devb-eide | PPC, X86 | MDMA 2 | |
| XILINX | W221 | 0x10EE: N/A | devb-eide | ARM, MIPS, PPC, SH4, X86 | | |
| Y-E Data | Flash Buster-U | 0x057b:0x0000 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Zarva | MP3 Player | 0x066f:0x8257 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB MP3 player | |