

Block IO

| Vendor | Model | Vendor:DeviceID | Drivers | Supported CPU | Notes |
|-----------|--------------------------|-----------------|------------|-----------------------------|--|
| Acer Labs | M5229 | 10b9: 5229 | devb-eide | X86 | rev 0x19-0xC1 UDMA 2 |
| Acer Labs | ThunderX | 0x0402:0x5621 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB IDE Disk |
| Acer Labs | M5229 | 10b9: 5229 | devb-eide | X86 | rev 0xC2-0xC3 UDMA 4 |
| Acer Labs | M5229 | 10b9: 5229 | devb-eide | X86 | rev 0xC4 UDMA 5 |
| Acer Labs | M5287 | 10b9: 5287 | devb-eide | X86 | SATA |
| Acer Labs | M5289 | 10b9: 5289 | devb-eide | X86 | SATA |
| ACOM | FlashKey | 0x0c0b:0xb001 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive |
| Adaptec | AHA-1510 A | N/A | devb-aha2 | X86 | PIO ISA SCSI host adapter without BIOS |
| Adaptec | AHA-1520 A | N/A | devb-aha2 | X86 | PIO ISA SCSI host adapter |
| Adaptec | AHA-1522 A | N/A | devb-aha2 | X86 | PIO ISA SCSI host adapter with floppy controller |
| Adaptec | AHA-1522 B | N/A | devb-aha2 | X86 | PIO ISA SCSI host adapter |
| Adaptec | AHA-1530 P | N/A | devb-aha2 | X86 | PIO ISA-to- Fast SCSI host adapter |
| Adaptec | AHA-1540 A | N/A | devb-aha4 | X86 | Bus master ISA SCSI host adapter. |
| Adaptec | AHA-1540 B | N/A | devb-aha4 | X86 | Bus master ISA SCSI host adapter. |
| Adaptec | AHA-1540 C | N/A | devb-aha4 | X86 | Bus master ISA SCSI host adapter. |
| Adaptec | AHA-1540 CF | N/A | devb-aha4 | X86 | Bus master ISA-to-Fast SCSI host adapter. |
| Adaptec | AHA-1542 A | N/A | devb-aha4 | X86 | Bus master ISA SCSI host adapter with floppy controller. |
| Adaptec | AHA-1542 B | N/A | devb-aha4 | X86 | Bus master ISA SCSI host adapter with floppy controller. |

| | | | | | | |
|---------|-------------|-----|-----------|-----|---|--|
| Adaptec | AHA-1542 C | N/A | devb-aha4 | X86 | Bus master ISA SCSI host adapter with floppy controller. | |
| Adaptec | AHA-1542 CF | N/A | devb-aha4 | X86 | Bus master ISA-to-Fast SCSI host adapter with floppy controller | |
| Adaptec | AHA-2740 | N/A | devb-aha7 | X86 | Bus master EISA-to-Fast SCSI host adapterx09 | |
| Adaptec | AHA-2740 T | N/A | devb-aha7 | X86 | TwinChannel Bus master EISA-to-Fast SCSI host adapter | |
| Adaptec | AHA-2740 W | N/A | devb-aha7 | X86 | Bus master EISA-to-Fast and Wide SCSI host adapter | |
| Adaptec | AHA-2742 | N/A | devb-aha7 | X86 | Bus master EISA-to-Fast SCSI host adapter with floppy controller | |
| Adaptec | AHA-2742 T | N/A | devb-aha7 | X86 | TwinChannel Bus master EISA-to-Fast SCSI host adapter with floppy controller | |
| Adaptec | AHA-2742 W | N/A | devb-aha7 | X86 | Bus master EISA-to-Fast and Wide SCSI host adapter with floppy controller | |
| Adaptec | AHA-2840 A | N/A | devb-aha7 | X86 | Bus master VL-to-Fast SCSI host adapter | |
| Adaptec | AHA-2842 A | N/A | devb-aha7 | X86 | Bus master VL-to-Fast SCSI host adapter with floppy controller | |

| | | | | | | |
|---------|-----------------|------------------|-----------|----------------|--|--|
| Adaptec | AHA-2902 E | 9004: 5078 | devb-aha8 | MIPS, PPC, X86 | PCI-to-Fast SCSI (non-bootable, external) . No Support for MIPS BE | |
| Adaptec | AHA-2902 I | 9004: 5078 | devb-aha8 | MIPS, PPC, X86 | PCI-to-Fast SCSI (non-bootable, internal) . No Support for MIPS BE | |
| Adaptec | AHA-2904 | 9004: 5078 | devb-aha8 | MIPS, PPC, X86 | PCI-to-Fast SCSI (non-bootable) | |
| Adaptec | AHA-2910 | 9004: 5078 | devb-aha8 | MIPS, PPC, X86 | PCI-to-Fast SCSI (non-bootable) . No Support for MIPS BE | |
| Adaptec | AHA-29160 | 9005: 0080 | devb-aha8 | MIPS, PPC, X86 | PCI-to-Ultra160 SCSI. No Support for MIPS BE | |
| Adaptec | AHA-2930CVA | 9004: 3868, 3869 | devb-aha8 | MIPS, PPC, X86 | No Support for MIPS BE | |
| Adaptec | AHA-2930 U | 9004: 3860 | devb-aha8 | MIPS, PPC, X86 | PCI-to-Ultra Fast SCSI. No Support for MIPS BE | |
| Adaptec | AHA-2930 UW | 9004: 8878, 7888 | devb-aha8 | MIPS, PPC, X86 | PCI-to-Ultra Wide Fast SCSI. No Support for MIPS BE | |
| Adaptec | AHA-2940 | 9004: 7178 | devb-aha8 | MIPS, PPC, X86 | Bus master PCI-to-Fast SCSI host adapter. No Support for MIPS BE | |
| Adaptec | AHA-2940 AU | 9004: 6178 | devb-aha8 | MIPS, PPC, X86 | Bus master PCI-to-Fast SCSI host adapter. No Support for MIPS BE | |
| Adaptec | AHA-2940 U | 9004: 8178 | devb-aha8 | MIPS, PPC, X86 | PCI-to-Ultra Single-ended SCSI. No Support for MIPS BE | |
| Adaptec | AHA-2940 U Dual | N/A | devb-aha8 | MIPS, PPC, X86 | Dual Channel PCI-to-Ultra | |

| | | | | | |
|---------|------------------|----------------|-----------|----------------|--|
| | | | | | Wide Internal Single-ended SCSI with 50-pin external connector. No Support for MIPS BE |
| Adaptec | AHA-2940 UW | 0x9004: 0x8178 | devb-aha8 | MIPS, PPC, X86 | PCI-to-Ultra Wide Single-ended SCSI. No Support for MIPS BE |
| Adaptec | AHA-2940 UW Dual | N/A | devb-aha8 | MIPS, PPC, X86 | Dual Channel PCI-to-Ultra Wide Internal Single-ended SCSI with Wide external connector. No Support for MIPS BE |
| Adaptec | AHA-2940 W | 9004: 7178 | devb-aha8 | MIPS, PPC, X86 | Bus master PCI-to-Fast and Wide SCSI host adapter. No Support for MIPS BE |
| Adaptec | AHA-2944 | 0x9004: 0x7478 | devb-aha8 | MIPS, PPC, X86 | PCI-to-Fast Differential SCSI. No Support for MIPS BE |
| Adaptec | AHA-2944 UW | 9004: 8478 | devb-aha8 | MIPS, PPC, X86 | PCI-to-Ultra Wide Differential SCSI. No Support for MIPS BE |
| Adaptec | AHA-2944 W | N/A | devb-aha8 | MIPS, PPC, X86 | PCI-to-Fast and Wide Differential SCSI. No Support for MIPS BE |
| Adaptec | AHA-3940 | 0x9004: 0x7278 | devb-aha8 | MIPS, PPC, X86 | Bus master PCI-to-Fast SCSI host adapter. No Support for MIPS BE |
| Adaptec | AHA-3940 AU | N/A | devb-aha8 | MIPS, PPC, X86 | MultiChannel PCI-to-Ultra SCSI. No |

| | | | | | |
|---------|---------------|----------------|-----------|----------------|---|
| | | | | | Support for MIPS BE |
| Adaptec | AHA-3940 A UW | N/A | devb-aha8 | MIPS, PPC, X86 | MultiChannel PCI-to-Ultra Wide SCSI. No Support for MIPS BE |
| Adaptec | AHA-3940 AUWD | N/A | devb-aha8 | MIPS, PPC, X86 | MultiChannel PCI-to-Ultra Wide SCSI with dual external connectors. No Support for MIPS BE |
| Adaptec | AHA-3940 U | 0x9004: 0x8278 | devb-aha8 | MIPS, PPC, X86 | MultiChannel PCI-to-Ultra SCSI |
| Adaptec | AHA-3940U2x | 0x9005: 0x0050 | devb-aha8 | MIPS, PPC, X86 | Ultra2 SCSI Adapter. No Support for MIPS BE |
| Adaptec | AHA-3940 UW | 9004: 8278 | devb-aha8 | MIPS, PPC, X86 | Bus master PCI-to-Fast and Wide SCSI host adapter. No Support for MIPS BE |
| Adaptec | AHA-3940 UWD | 9004: 8278 | devb-aha8 | MIPS, PPC, X86 | MultiChannel PCI-to-Ultra Wide SCSI with Dual external connectors. No Support for MIPS BE |
| Adaptec | AHA-3940 W | 9004: 7278 | devb-aha8 | MIPS, PPC, X86 | Bus master PCI-to-Fast and Wide SCSI host adapter. No Support for MIPS BE |
| Adaptec | AHA-3944 | 0x9004: 0x7578 | devb-aha8 | MIPS, PPC, X86 | MultiChannel PCI-to-Differential SCSI host adapter. No Support for MIPS BE |
| Adaptec | AHA-3944 U | 0x9004: 0x8578 | devb-aha8 | MIPS, PPC, X86 | Fast-Wide/ Ultra-Wide Differential SCSI host adapter. No |

| | | | | | |
|---------|------------------|------------------------------|-----------|-------------------|---|
| | | | | | Support for MIPS BE |
| Adaptec | AHA-3944 W | 0x9004: 0x7578 | devb-aha8 | MIPS, PPC, X86 | MultiChannel PCI-to-Wide Differential SCSI. No Support for MIPS BE |
| Adaptec | AHA-3944 AUWD | N/A | devb-aha8 | MIPS, PPC, X86 | No Support for MIPS BE |
| Adaptec | AHA-3944 UWD | 9004: 8578 | devb-aha8 | MIPS, PPC, X86 | MultiChannel PCI-to- Ultra Wide Differential SCSI with Dual external connectors. No Support for MIPS BE |
| Adaptec | AHA-3950U2x | 0x9005: 0x0050, 0x0051 | devb-aha8 | MIPS, PPC, X86 | Ultra2 SCSI Adapter. No Support for MIPS BE |
| Adaptec | AHA-4944 UW | 0x9004: 0x7678, 0x8678 | devb-aha8 | MIPS, PPC, X86 | Quad Channel PCI-to-Ultra and Wide Differential SCSI. No Support for MIPS BE |
| Adaptec | AHA-4944 W | 9004: 7678 | devb-aha8 | MIPS, PPC, X86 | Quad Channel PCI-to-Fast and Wide Differential SCSI |
| Adaptec | AIC-6260 | N/A | devb-aha2 | X86 | PIO single chip SCSI host adapter. |
| Adaptec | AIC-6360 | N/A | devb-aha2 | X86 | PIO single chip SCSI host adapter. |
| Adaptec | AIC-755X | 9004: 5075 | devb-aha8 | MIPS, PPC, X86 | |
| Adaptec | AIC-7560 | 0x9004: 0x6075 | devb-aha8 | MIPS, PPC, X86 | |
| Adaptec | AIC-7770 | N/A | devb-aha7 | X86 | Bus master single chip SCSI host adapter. |
| Adaptec | AIC-7850P | 0x9004: 0x5078 | devb-aha8 | MIPS, PPC, X86 | Bus master single chip PCI-SCSI host adapter. No |

| | | | | | | |
|---------|------------|---|--------------|----------------|--|--|
| | | | | | Support for MIPS BE | |
| Adaptec | AIC-7855 | 9004: 5578 | devb-aha8 | MIPS, PPC, X86 | Single-chip PCI-to-Fast SCSI. No Support for MIPS BE | |
| Adaptec | AIC-7856 | 9004: 5678 | devb-aha8 | MIPS, PPC, X86 | Single-chip PCI-to-Fast SCSI. No Support for MIPS BE | |
| Adaptec | AIC-7860 | 0x9004: 0x6078, 0x7860, 0x6278 | devb-aha8 | MIPS, PPC, X86 | PCI SCSI Controller. No Support for MIPS BE | |
| Adaptec | AIC-7861 | 0x9004: 0x6178 | devb-aha8 | MIPS, PPC, X86 | PCI SCSI Controller. No Support for MIPS BE | |
| Adaptec | AIC-785X | | devb-adpu360 | MIPS, PPC, X86 | SCSI Ctrlr. No Support for MIPS BE | |
| Adaptec | AIC-7870 | 0x9004: 0x7078, 0x6778 | devb-aha8 | MIPS, PPC, X86 | Bus master single chip PCI-SCSI host adapter. No Support for MIPS BE | |
| Adaptec | AIC-787X | 0x9004: 0x7778 | devb-aha8 | MIPS, PPC, X86 | PCI SCSI Controller. Support for this controller is also found in the devb-adpu360 driver. | |
| Adaptec | AIC-7880 | 0x9004: 0x8078 | devb-aha8 | MIPS, PPC, X86 | Integrated bus master single chip PCI Ultra Wide SCSI host adapter | |
| Adaptec | AIC-7883 U | 9004: 8378 | devb-aha8 | MIPS, PPC, X86 | Ultra-Wide SCSI host adapter. No Support for MIPS BE | |
| Adaptec | AIC-788X | 0x9004: 0x8778 | devb-aha8 | MIPS, PPC, X86 | Ultra-Wide SCSI host adapter. Support for this controller is also found in the devb- | |

| | | | | | |
|---------|------------|--|--------------|----------------|--|
| | | | | | adpu360 driver. |
| Adaptec | AIC-7890 | 9004: 7890, 001F | devb-aha8 | MIPS, PPC, X86 | Ultra 2 SCSI host adapter. No Support for MIPS BE |
| Adaptec | AIC-7890AB | 0x9005: 0x0010 | devb-aha8 | MIPS, PPC, X86 | Ultra-Wide SCSI host adapter. No Support for MIPS BE |
| Adaptec | AIC-7891 | 9005: 001F | devb-aha8 | MIPS, PPC, X86 | 64Bit PCI Ultra2 SCSI host adapter. No Support for MIPS BE |
| Adaptec | AIC-7895 | 0x9004: 0x7895 | devb-aha8 | MIPS, PPC, X86 | Single-chip PCI-to- MultiChannel Ultra Wide SCSI. No Support for MIPS BE |
| Adaptec | AIC-7896 | 9005: 005F | devb-aha8 | MIPS, PPC, X86 | Ultra2 SCSI Controller. No Support for MIPS BE |
| Adaptec | AIC-7897 | 9005: 005F | devb-aha8 | MIPS, PPC, X86 | Ultra2 SCSI Controller. No Support for MIPS BE |
| Adaptec | AIC-7899 | 0x9004: 0x7891, 0x7892, 0x7893, 0x7894, 0x7896, 0x7897. 0x9005: 0x0020, 0x0030, 0x002F, 0x003F, 0x00CF | devb-aha8 | MIPS, PPC, X86 | Ultra2-Wide SCSI host adapter. No Support for MIPS BE |
| Adaptec | AMM-1570 | N/A | devb-aha2 | X86 | PIO ISA-to-Fast SCSI host adapter |
| Adaptec | AIC-7901 | 0x9005; 0x801E | devb-adpu320 | MIPS, PPC, X86 | Single-Channel PCI-X to Ultra320 SCSI Controller |
| Adaptec | AIC-7902 | 0x9005; 0x801F | devb-adpu320 | MIPS, PPC, X86 | Dual-Channel PCI-X to Ultra320 SCSI |

| | | | | | | |
|---------|------------------|--|--------------|-------------------|--|--|
| Adaptec | 29320A-R | 0x9005; 0x8000 | devb-adpu320 | MIPS, PPC, X86 | 64-bit 133 MHz PCI-X, single-channel Ultra320 SCSI card | |
| Adaptec | AIC-786X | 0x9004: 0x6478, 0x6578, 0x6678 | devb-aha8 | MIPS, PPC, X86 | SCSI Ctrlr. Support for this chipset is also found in the devb-adpu360 driver. | |
| Adaptec | AIC-789X | 0x9005; 0x8778, 0x0020, 0x0030, 0x003F, 0x001F, 0x002F, 0x0060, 0x0070, 0x005F, 0x006F, 0x007F, 0x008F, 0x009F, 0x00AF, 0x00BF, 0x0080, 0x0090, 0x00A0, 0x00B0, 0x00DF, 0x00EF, 0x00FF, 0x00FF, 0x00D0, 0x00E0, 0x00F0 | devb-aha8 | MIPS, PPC, X86 | Ultra-Wide SCSI host adapter. Support for this controller is also found in the devb- adpu360 driver. | |
| Adaptec | AHA-2930U | 0x9004: 0x3860 | devb-aha8 | MIPS, PPC, X86 | AIC-2930U Ultra SCSI | |
| Adaptec | AHA-2940/2940W | 0x9004: 0x7178 | devb-aha8 | MIPS, PPC, X86 | | |
| Adaptec | AHA-4944W/4944WU | 0x9004: 0x7678, 0x3B78, 0xEC78 | devb-aha8 | MIPS, PPC, X86 | | |
| Adaptec | AHA-2944UW | 0x9004: 0x8478 | devb-aha8 | MIPS, PPC, X86 | | |
| Adaptec | AIC-7888 | 0x9004: 0x8878 | devb-aha8 | MIPS, PPC, X86 | | |
| Adaptec | AIC-7892B | 0x9005: 0x0081 | devb-aha8 | MIPS, PPC, X86 | | |
| Adaptec | AIC-7899A | 0x9005: 0x00C0 | devb-aha8 | MIPS, PPC, X86 | | |

| | | | | | | |
|---------------------------------|---|---------------|------------|--------------------------|--|--|
| Alcor Micro Corp. | Acer Flash drive | 0x58f:0x9382 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Algorithmics | P-5064 | N/A | devf-p5064 | MIPS | Flash filesystem support for the MIPS QED evaluation board. No Support for MIPS BE | |
| AMD | AM-53C974 | 1022: 2020 | devb-amd | MIPS, X86 | Bus master PCI-to-Fast SCSI host adapter. No Support for MIPS BE | |
| AMD | AM-79C974 KC | N/A | devb-amd | MIPS, X86 | Bus master PCI-to-Fast SCSI host adapter. No Support for MIPS BE | |
| AMD | PCB-756 | 1022: 7409 | devb-eide | X86 | UDMA 4 (untested) | |
| AMD | PCB-766 | 1022: 7411 | devb-eide | X86 | UDMA 5 (untested) | |
| AMD | PCB-768 | 1022: 7441 | devb-eide | X86 | UDMA 5 | |
| Apacer Technology, Inc. | Handy Steno 2.0 (256MB) | 0x1005:0xb113 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Apacer Technology, Inc. | 1G flash key (Handy HA202) | 0x1005:0xb113 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash key | |
| Apacer Technology, Inc. | Handy Steno HT202 | 0x1005:0xb113 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Apple | 30GB iPod Photo | 0x05ac:0x1209 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB iPod | |
| Apple | iPod MP3 Player | 0x05ac:0x1300 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB iPod | |
| ATI | IXP-150/200/250 | 0x1002:0x4349 | devb-eide | X86 | UDMA 5 | |
| Buffallo | 11in1 CardReader/Writer | 0x0411:0x0058 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB Card Reader | |
| BusLogic/ Mylex | BT-440C | N/A | devb-btmm | X86 | Bus master VL SCSI host adapter. | |
| BusLogic/ Mylex | BT-445C | N/A | devb-btmm | X86 | Bus master VL SCSI host adapter with floppy controller. | |

| | | | | | | |
|------------------------------------|------------------------------------|---------------|------------|-----------------------------|--|--|
| BusLogic/ Mylex | BT-542B | N/A | devb-btmm | X86 | Bus master ISA SCSI host adapter with floppy controller. | |
| BusLogic/ Mylex | BT-542D | N/A | devb-btmm | X86 | Bus master ISA-to- Fast SCSI host adapter with floppy controller. | |
| BusLogic/ Mylex | BT-545C | N/A | devb-btmm | X86 | Bus master ISA SCSI host adapter with floppy controller. | |
| BusLogic/ Mylex | BT-545S | N/A | devb-btmm | X86 | Bus master ISA-to- Fast SCSI host adapter with floppy controller. | |
| BusLogic/ Mylex | BT-646S | N/A | devb-btmm | X86 | Bus master MCA SCSI host adapter. | |
| BusLogic/ Mylex | BT-747S | N/A | devb-btmm | X86 | Bus master EISA SCSI host adapter. | |
| BusLogic/ Mylex | BT-946C | 4B10: 1040 | devb-btmm | X86 | Bus master PCI-to- Fast SCSI host adapter with floppy controller. | |
| Canon | Powershot A70 (CF card) | 0x04a9:0x30b5 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB camera | |
| CMD | CMD-646 | 1095: 0646 | devb-eide | X86 | UDMA 33 | |
| CMD | CMD-648 | 1095: 0648 | devb-eide | X86 | UDMA 33, UDMA 66 | |
| CMD | CMD-649 | 1095: 0649 | devb-eide | X86 | UDMA 33, UDMA 66, UDMA 100 | |
| Comstar | Comstar 32M flash disk | 0x090a:0x14c1 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Corsair | Flash Voyager (1G) | 0x067b:0x2517 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Creative Labs | Soundblaster 16 SCSI | N/A | devb-aha2 | X86 | PIO ISA SCSI host adapter | |
| Creative Labs | MuVo MP3 Player | 0x041e:0x4120 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB MP3 player | |
| Cypress | Cypress hard drive | 0x04b4:0x6830 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB hard drive | |
| Cyrix | Cx5530 | 1078: 0102 | devb-eide | X86 | UDMA 33 | |

| | | | | | | |
|--------------------------------|---|---------------|--------------|--------------------------|--|--|
| Dura Micro | DMI SA2 | 0x0c0b:0xb001 | devu-mass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Flash | CFI NOR Flash | N/A | devf-generic | ARM, MIPS, PPC, SH4, X86 | Support all standard CFI Nor Flash parts | |
| Geek Squad | Geek Squad 1.0 GB and Memory Traveldrive | 0x08ec:0x0016 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| GemLight | UPD720130 (USB IDE Disk) | 0x14c2:0x0001 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB IDE Disk | |
| Generic | IDE/EIDE/ATAPI | N/A | devb-eide | X86 | Supports most EIDE interfaces. | |
| Generic | Generic 16M flash key | 0x1043:0x8006 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Generic | Generic 128M flash key and Transcend JetFlash | 0x058f:0x9380 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Generic | Generic USB Flash Part | 0x0ef5:0x2202 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Generic | FlashKey | 0x0d7d:0x0100 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Generic | USB Mass Storage Devices | n/a | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB Mass storage Devices compliant with Mass Storage Specifications Overview (Rev 1.2), Bulk Only (Rev 1.0), CBI Specification (Rev 1.1), UFI Command Specification (Rev 1.0) (see http://www.usb.org/developers/devclass_docs) | |
| Hewlett-Packard | PhotoSmart 945 Digital Camera | 0x03f0:0x4002 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB camera | |
| HighPoint Tech | HPT-366 | 1103: 0004 | devb-eide | X86 | rev 0x01 UDMA 4 (untested) | |
| HighPoint Tech | HPT-370 | 1103: 0004 | devb-eide | X86 | rev 0x3+ UDMA 5 | |
| HighPoint Tech | HPT-372 | 1103: 0005 | devb-eide | X86 | UDMA 6 | |

| | | | | | | |
|-------------------|-----------------------|-------------------|------------|-----------------------------|--------------------------------------|--|
| HighPoint Tech | HPT-374 | 1103: 0008 | devb-eide | X86 | UDMA 6 | |
| Hyundai | 2.2 Gig Flash Disk | 0x0ea0:0x2136 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB Flash Drive | |
| IBM | CD-ROM | 0x04b3:0x4427 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB CD-ROM | |
| Intel | 82371FB (PIIX) | 8086: 1230 | devb-eide | ARM, MIPS, PPC, SH4, X86 | BIOS Mode transfers | |
| Intel | 82371SB (PIIX3) | 8086: 7010 | devb-eide | ARM, MIPS, PPC, SH4, X86 | MDMA 2 | |
| Intel | 82371AB (PIIX4) | 8086: 7111 | devb-eide | PPC, X86 | | |
| Intel | 82801AA (ICH) | 8086: 2411 | devb-eide | ARM, MIPS, PPC, SH4, X86 | UDMA 4 | |
| Intel | 82801AB (ICH0) | 8086: 2421 | devb-eide | ARM, MIPS, PPC, SH4, X86 | UDMA 4 | |
| Intel | 82801BA (ICH2) | 8086: 244A | devb-eide | ARM, MIPS, PPC, SH4, X86 | UDMA 5 | |
| Intel | 82801BAM (ICH2-M) | 8086: 244B | devb-eide | ARM, MIPS, PPC, SH4, X86 | UDMA 5 | |
| Intel | 82801CA (ICH3-S) | 8086: 248B | devb-eide | ARM, MIPS, PPC, SH4, X86 | UDMA 5 | |
| Intel | 82801CAM (ICH3-M) | 8086: 248A | devb-eide | ARM, MIPS, PPC, SH4, X86 | UDMA 5 | |
| Intel | 82801DB (ICH4) | 8086: 24CB | devb-eide | ARM, MIPS, PPC, SH4, X86 | UDMA 5 | |
| Intel | 82801EB (ICH5) | 0x8086: 0x24D1 | devb-eide | X86 | SATA. (released in 6.3.0 SP3) | |
| Intel | 82801EB (ICH5) | 0x8086: 0x24DB | devb-eide | X86 | UDMA 5 (released in 6.3.0 SP3) | |
| Intel | 82801ER (ICH5R) | 0x8086: 0x24DF | devb-eide | PPC, X86 | SATA. (released in 6.3.0 SP3) | |
| Intel | 82801FB (ICH6) | 0x8086: 0x2651 | devb-eide | PPC, X86 | SATA. (released in 6.3.0 SP3) | |
| Intel | 82801FR (ICH6R) | 0x8086: 0x2652 | devb-eide | PPC, X86 | SATA. (released in 6.3.0 SP3) | |
| Intel | 82801FB (ICH6) | 0x8086: 0x266F | devb-eide | PPC, X86 | UDMA 5 (released in 6.3.0 SP3) | |
| Intel | 82801FBM (ICH6M) | 0x8086: 0x2653 | devb-eide | PPC, X86 | SATA (released in 6.3.0 SP3) | |
| Intel | 82801GB (ICH7) | 0x8086: 0x27DF | devb-eide | PPC, X86 | UDMA 5 (released in 6.3.0 SP3) | |
| Intel | 82801GB (ICH7) | 0x8086: 0x27C0 | devb-eide | PPC, X86 | SATA (released in 6.3.0 SP3) | |

| | | | | | | |
|----------|--|-------------------|------------|-----------------------------|-------------------------------------|--|
| Intel | 82801GB (ICH7) | 0x8086: 0x27C4 | devb-eide | PPC, X86 | SATA (released in 6.3.0 SP3) | |
| Intel | 6300ESB (ICH) | 0x8086: 0x25A2 | devb-eide | X86 | UDMA 5 (release in 6.3.0 SP3) | |
| Intel | 6300ESB (ICH) | 0x8086: 0x25A3 | devb-eide | X86 | SATA (release in 6.3.0 SP3) | |
| Intel | 82801FB (ICH6) | 0x8086: 0x2651 | devb-ahci | PPC, X86 | SATA (released in 6.3.0 SP3) | |
| Intel | 82801FBM (ICH6M) | 0x8086: 0x2653 | devb-ahci | PPC, X86 | SATA (released in 6.3.0 SP3) | |
| Intel | 82801GB (ICH7) | 0x8086: 0x27c1 | devb-ahci | PPC, X86 | SATA (released in 6.3.0 SP3) | |
| Intel | 82801GBM (ICH7M) | 0x8086: 0x27c5 | devb-ahci | PPC, X86 | SATA (released in 6.3.0 SP3) | |
| Iomega | ZIP100 | 0x059b:0x0001 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB zip drive | |
| Iomega | ZIP250 | 0x059b:0x0030 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB zip drive | |
| Iomega | ZIP750 | 0x059b:0x0035 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB zip drive | |
| Iomega | Zip Drive 100M | 0x059b:0x0001 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB zip drive | |
| Kingston | USB Drive | 0x04e8:0x0100 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Kingston | Data Traveler 2.0, 1G | 0x0930:0x653d | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Kingston | Data Traveler Elite, 1G | 0x08ec:0x0015 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Kingston | DiskOnKey 1G | 0x08ec:0x0012 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Kingston | DiskOnKey 256M | 0x0951:0x1600 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Lacie | External Harddrive | 0x059f:0x0321 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB hard drive | |
| Lexar | JumpDrive Pro | 0x05dc:0xa400 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Lexar | JumpDrive Trio | 0x05dc:0xb013 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Lexar | Lexar flash drive | 0x0781:0x0810 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB compact flash | |
| Lexar | Jumpdrive (64M) | 0x05dc:0x0080 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Lexar | MP3 Player 512 external flash card | 0x05dc:0x4d40 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB MP3 player | |
| Lexar | Jumpdrive | 0x05dc:0xa400 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |

| | | | | | | |
|------------------------|--|---------------|-------------|--------------------------|---|--|
| Lyra | MP3 Player | 0x069b:0x070c | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB MP3 player | |
| M-Systems | DiskonKey | 0x8ec:0x10 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| M-Systems | DiskonKey V2 | 0x8ec:0x11 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| M-Systems | DiskGo | 0x8ec:0x12 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| M-Systems | DiskOnKey 16MB and 64MB | 0x08ec:0x0010 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drives | |
| M-Systems | 64M DiskOnKey | 0x08ec:0x0011 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| M-Systems | 9 in 1 Accelerate Card Reader | 0x05e3:0x0760 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB card reader | |
| Marvell | 88SX5080 | 0x11ab:0x5080 | devb-mvSata | X86 | SATA (released in 6.3.0 SP3) | |
| Marvell | 88SX5081 | 0x11ab:0x5081 | devb-mvSata | X86 | SATA (released in 6.3.0 SP3) | |
| Marvell | 88SX5040 | 0x11ab:0x5040 | devb-mvSata | X86 | SATA (released in 6.3.0 SP3) | |
| Marvell | 88SX5041 | 0x11ab:0x5041 | devb-mvSata | X86 | SATA (released in 6.3.0 SP3) | |
| Maxtor | 3000LE hard drive | 0x0d49:0x3010 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB hard drive | |
| Mobil | Mobil Disk Z4 (512M) and GXT (1G, 2G) | 0x126f:0x0161 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| National Semiconductor | CS-5530 | 0x100B: N/A | devb-eide | ARM, MIPS, PPC, SH4, X86 | | |
| NCR/Symbios | NCR-53c810 | N/A | devb-ncr8 | X86 | Bus master PCI-to-Fast SCSI host adapter. | |
| NCR/Symbios | NCR-53C810A | N/A | devb-ncr8 | X86 | Bus master PCI-to-Fast SCSI host adapter. | |
| NCR/Symbios | NCR-53c815 | N/A | devb-ncr8 | X86 | Bus master PCI-to-Fast SCSI host adapter. | |
| NCR/Symbios | NCR-53c820 | N/A | devb-ncr8 | X86 | Bus master PCI-to-Fast SCSI host adapter. | |
| NCR/Symbios | NCR-53c825 | N/A | devb-ncr8 | X86 | Bus master PCI-to-Fast | |

| | | | | | | |
|---------------------|-----------------------------------|---------------------|------------|--------------------------|---|--|
| | | | | | SCSI host adapter. | |
| NCR/Symbios | NCR-53c860 | N/A | devb-ncr8 | X86 | Bus master PCI-to-Fast SCSI host adapter. | |
| NCR/Symbios | NCR-53c875 | N/A | devb-ncr8 | X86 | Bus master PCI-to-Fast SCSI host adapter. | |
| NCR/Symbios | NCR-53c885 | N/A | devb-ncr8 | X86 | Bus master PCI-to-Fast SCSI host adapter | |
| NCR/Symbios | NCR-53c895 | N/A | devb-ncr8 | X86 | Bus master PCI-to-Fast SCSI host adapter. | |
| NCR/Symbios | NCR-53c895A | 0x1000: 0x0012 | devb-ncr8 | X86 | PCI to Ultra2 SCSI Controller | |
| NCR/Symbios | NCR-53c896 | N/A | devb-ncr8 | X86 | Bus master PCI-to-Fast SCSI host adapter. | |
| Nexdisk | Nexdisk PSD 56(128M) | 0x09a6:0x8001 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Nikon | Nikon Digital Camera E5700 | 0x04b0:0x0010 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB Camera | |
| Nikon | Digital Camera | 0x04b0:0x010C | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB Camera | |
| Nikon | Coolpix 8800VH | 0x04b0:0x0127 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB camera | |
| nVidia | nForce MCP | 0x10DE: 0x01bc | devb-eide | X86 | UDMA 5 (untested) | |
| Olympus | D-510 Zoom Digital Camera | 0x07b4:0x0105 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB Camera | |
| Ours Technology Inc | OTI-6803 Solid Flash Disk | 0x0ea0:0x6803 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Panasonic | Panasonic DMC FZ10 Digital Camera | 0x04da:0x2372 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB camera | |
| PC Tech | RZ1000 | 1042: 1000, 1001 | devb-eide | X86 | PCI EIDE Controller | |
| Phison | Phison USB Disk Pro | 0x0d7d:0x1320 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB disk | |
| Pine | PT-CW320A CD-ROM | 0x04a5:0x6006 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB CD-ROM | |
| PNY | PNY Attache 1G | 0x0930:0x6534 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| PNY | PNY Attache 512M | 0x0930:0x6533 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |

| | | | | | | |
|-------------------------------------|--------------------------------------|---------------|------------|--------------------------|--------------------------------------|--|
| Prolific Technology Inc. | USB flash | 0x067b:0x2517 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Promise | PDC-20262 | 105A: 4D38 | devb-eide | X86 | UDMA 4 | |
| Promise | PDC-20267 | 105A: 0x4D30 | devb-eide | X86 | UDMA 4 | |
| Promise | PDC-20265 | 105A: 0D30 | devb-eide | X86 | UDMA 5 | |
| Promise | PDC-20269 | 105A: 4D69 | devb-eide | X86 | UDMA 5 | |
| RAM | Ram Disk | N/A | devb-ram | ARM, MIPS, PPC, SH4, X86 | Ram filesystem using block interface | |
| RAM | Ram Disk | N/A | devf-ram | ARM, MIPS, PPC, SH4, X86 | Ram filesystem using flash interface | |
| Samsung | MP3 Player | 0x04e8:0x5026 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB MP3 player | |
| SanDisk Corporation | Cruzer Micro | 0x0781:0x7112 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| SanDisk Corporation | Cruzer Micro | 0x0781:0x5151 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| SanDisk Corporation | Cruzer Mini 512MB & 1GB | 0x0781:0x5150 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| SanDisk Corporation | Cruzer Mini | 0x0781:0x7103 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| SanDisk Corporation | Cruzer (128M) | 0x0781:0x8888 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| ScanLogic | SL11R (USB IDE Disk) | 0x04ce:0x0002 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB hard drive | |
| SCM Microsystems (Shuttle) | E-USB ATA Bridge (Flash Card Reader) | 0x04e6:0x0001 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB card reader | |
| SCM Microsystems (Shuttle) | CF Multi-card reader | 0x04e6:0x0311 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB card reader | |
| SCM Microsystems (Shuttle) | ORCA Multi-card reader | 0x04e6:0x0325 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB card reader | |
| ServerWorks | CSB5 | 1166: 0212 | devb-eide | X86 | UDMA 4 (untested) | |
| ServerWorks | OSB4 | 1166: 0211 | devb-eide | X86 | UDMA 2 | |
| ServerWorks | CSB5 | 1166: 0212 | devb-eide | X86 | Revision 0x92+ UDMA 5 | |
| SIS | SiS-5513 | 0x1039:0x5513 | devb-eide | X86 | rev 0xD0 UDMA 2/4 | |
| SIS | SiS-5517 | 0x1039:0x5517 | devb-eide | X86 | UDMA 6 | |
| SIS | SiS-5518 | 0x1039:0x5518 | devb-eide | X86 | UDMA 6 | |
| SIS | SiS-180 | 0x1039:0x0180 | devb-eide | X86 | SATA | |
| SIS | SiS-181 | 0x1039:0x0181 | devb-eide | X86 | SATA | |
| SMI (Silicon Motion) | DiskOnKey | 0x090c:0x1000 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Sony | Sony USB Floppy Drive | 0x054c:0x002c | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB Floppy Drive | |

| | | | | | | |
|---------------------|--|---------------|------------|--------------------------|-----------------|--|
| Sony | Sony DSC-S30/S70/S75/F505V/F505/FD92 Cybershot/Mavica Digital Camera | 0x054c:0x0010 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB camera | |
| Sony | Sony HandyCam Memory Stick Reader | 0x054c:0x002e | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB card reader | |
| Sony | Micro Vault 256M Flash Key | 0x054c:0x0243 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Sony | Digital Camera | 0x054c:0x0010 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB Camera | |
| Sony | Camcorder | 0x054c:0x002e | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB camcorder | |
| Sony | DiskOnKey | 0x019e | devb-umass | ARM, MIPS, PPC, SH4, X86 | | |
| Sony | Floppy Disk Drive | 0x002c | devb-umass | ARM, MIPS, PPC, SH4, X86 | | |
| Spire | Spire USB 2.0 256MB & OCZ 1GB Rally | 0x0457:0x151 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| ST Microelectronics | STPC Consumer-II | 0x104A:0x021B | devb-eide | ARM, MIPS, PPC, SH4, X86 | | |
| Staples | Staples Relay 256MB | 0x0781:0x5202 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Staples | Smartdisk Firelite 60G | 0x0917:0x0207 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB hard drive | |
| SVDO | SVDO HVM-3 | | devb-eide | ARM, MIPS, PPC, SH4, X86 | | |
| Teac | CD-ROM | 0x0644:0x1000 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB CD-ROM | |
| Texas Instruments | OMAP 5905 | 0x104C: N/A | devb-eide | ARM, MIPS, PPC, SH4, X86 | | |
| Tone | Tone 5G 1 Inch Drive | 0x0ea0:0x2118 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB microdrive | |
| Transcend | TSJFlash | 0x058f:0x9380 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Transcend | TSJFlashA | 0x0c76:0x0005 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Trek | FlashKey | 0x0a16:0x9780 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| USB | Store n Go Pro 1GB | 0x08ec:0x0015 | devb-umass | ARM, MIPS, SH4, X86 | USB Flash Disk | |
| Vantec | Win NexStar 3 Port. Hard drive | 0x04b4:0x6830 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB hard drive | |
| Vantec | NexStar 2 IDE to USB @ | 0x0402:0x5621 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB hard drive | |

| | | | | | | |
|----------|-----------------------------------|----------------|---------------------|--------------------------|---|--|
| | Generic IDE to USB container | | | | | |
| Vantec | 7 in 1 card reader | 0x0402:0x5635 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB card reader | |
| Vantec | External disk enclosure NST 300UF | 0x067b:0x3507 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB disk drive | |
| Venturer | MP3 Digital Audio Player | 0x0419:0xa002 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB MP3 player | |
| VIA | 82C586B | 0x1106:0x0571 | devb-eide | X86 | 82686B PCI-ISA Bridge ver 0x40+ UDMA 5 | |
| VIA | 82C686B | 0x1106:0x0571 | devb-eide | ARM, MIPS, PPC, SH4, X86 | 8231 Bridge Chipset, UDMA 5 (untested) | |
| VIA | 82C686B | 0x1106:0x0571 | devb-eide | ARM, MIPS, PPC, SH4, X86 | 8233 Bridge Chipset, UDMA 5 (untested) | |
| VIA | 82C686B | 0x1106:0x0571 | devb-eide | ARM, MIPS, PPC, SH4, X86 | 8233C Bridge Chipset, UDMA 5 (untested) | |
| VIA | 82C686B | 0x1106:0x0571 | devb-eide | ARM, MIPS, PPC, SH4, X86 | 8233A Bridge Chipset, UDMA 6 | |
| VIA | 82C686B | 0x1106:0x0571 | devb-eide | ARM, MIPS, PPC, SH4, X86 | 8235A Bridge Chipset, UDMA 6 (untested) | |
| VIA | 82C686B | 0x1106:0x0571 | devb-eide | ARM, MIPS, PPC, SH4, X86 | 8237 Bridge Chipset, UDMA 6 (untested) | |
| VIA | 82C686B | 0x1106:0x0571 | devb-eide | ARM, MIPS, PPC, SH4, X86 | rev 0x6+, UDMA 2 | |
| VIA | VT8237 | 0x1106:0x3149 | devb-eide | ARM, MIPS, PPC, SH4, X86 | SATA | |
| Winbond | W83C553F | 0x10ad:0x0105 | devb-eide | PPC, X86 | MDMA 2 | |
| XILINX | W221 | 0x10EE: N/A | devb-eide | ARM, MIPS, PPC, SH4, X86 | | |
| Y-E Data | Flash Buster-U | 0x057b:0x0000 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB flash drive | |
| Zarva | MP3 Player | 0x066f:0x8257 | devb-umass | ARM, MIPS, PPC, SH4, X86 | USB MP3 player | |
| 3com | Venturer MP3 Digital Audio Player | 0x0419:0xa002 | devb-umass | ARM, MIPS, PPC, SH4, X86 | | |
| Aureal | AU8820 (Vortex) | 0x12eb: 0x0001 | deva-ctrl-vortex.so | X86 | | |

| | | | | | |
|---------------------------|--|----------------|---------------------------|----------------|--|
| Aureal | AU8830 (Vortex2) | 0x12eb: 0x0002 | deva-ctrl- vortex.so | X86 | |
| Cirrus | Crystal Sound CS4280 | 0x1013: 0x6003 | deva-ctrl- cs46xx.so | X86 | |
| Cirrus | Crystal Sound CS4281 | 0x1013: 0x6005 | deva-ctrl- cs4281.so | X86 | |
| Cirrus | Crystal Sound CS4610 | 0x1013: 0x6001 | deva-ctrl- cs46xx.so | X86 | |
| Cirrus | Crystal Sound CS4612 | 0x1013: 0x6003 | deva-ctrl- cs46xx.so | X86 | |
| Cirrus | Crystal Sound CS4614 | 0x1013: 0x6003 | deva-ctrl- cs46xx.so | X86 | |
| Cirrus | Crystal Sound CS4630 | 0x1013: 0x6003 | deva-ctrl- cs46xx.so | X86 | |
| Creative Labs | Creative Labs CT5880 | 0x1274: 0x5880 | deva-ctrl- audiopci.so | MIPS, PPC, X86 | |
| Creative Labs | Ensoniq ES1370 | 0x1274: 0x5000 | deva-ctrl- audiopci.so | MIPS, PPC, X86 | |
| Creative Labs | Ensoniq ES1371 | 0x1274: 0x1371 | deva-ctrl- audiopci.so | MIPS, PPC, X86 | |
| Creative Labs | Soundblaster Compatible | N/A | deva-ctrl-sb.so | X86 | |
| Embedded Planet | RPX-Lite (RedBox) | N/A | deva-ctrl-hiox.so | PPC | |
| ESS Technologies | ESS Solo-1 | 0x125d: 0x1969 | deva-ctrl- ess1938.so | X86 | |
| ESS Technologies | ESS Solo-1e | 0x125d: 0x1969 | deva-ctrl- ess1938.so | X86 | |
| ESS Technologies | ESS 1938 | 0x125d: 0x1969 | deva-ctrl- ess1938.so | X86 | |
| Intel | 82801AA (ICH) | 0x8086: 0x2415 | deva-ctrl-i8x0.so | X86 | |
| Intel | 82801AB (ICH0) | 0x8086: 0x2425 | deva-ctrl-i8x0.so | X86 | |
| Intel | 82801BA (ICH2) | 0x8086: 0x2445 | deva-ctrl-i8x0.so | X86 | |
| Intel | 82801CA (ICH3- S) | 0x8086: 0x2485 | deva-ctrl-i8x0.so | X86 | |
| Intel | 82801DB (ICH4) | 0x8086: 0x24cb | deva-ctrl-i8x0.so | X86 | |
| Intel | StrongArm sa1110 | N/A | deva-ctrl- sa1110.so | ARM | |
| Intel | StrongArm sa1111 | N/A | deva-ctrl- sa1111.so | ARM | |
| Intel | PXA250 | N/A | deva-ctrl- pxa250.so | ARM | |
| Intel | 82801EB (ICH5) | 0x8086; 0x24D5 | deva-ctrl-i8x0.so | X86 | |
| National Semiconductor | Geode (MediaGX) | N/A | deva-ctrl- geode.so | X86 | |
| National Semiconductor | Geode 1 | 0x1078: 0x0103 | deva-ctrl- geode.so | X86 | |
| National Semiconductor | Geode 5 | 0x100b: 0x0503 | deva-ctrl- geode.so | X86 | |
| NEC | VRC4173 | 0x1033: 0x00a6 | deva-ctrl- vrc4173.so | MIPS | |

| | | | | | |
|---------------------|--|----------------|------------------------------|-----|--|
| Neomagic | NM2380 (Neomagic 6) | 0x10c8: 0x8016 | deva-ctrl-nmg6.so | X86 | |
| Renesas | Tahoe | N/A | deva-ctrl-tahoe.so | SH4 | |
| Renesas | Amanda AC97 | N/A | deva-ctrl- amanda_ac97.so | SH4 | |
| Renesas | Amanda i2s | N/A | deva-ctrl- amanda_i2s.so | SH4 | |
| SIS | 963 | 0x1039; 0x7012 | deva-ctrl-i8x0.so | X86 | |
| Trident | 4DWave-DX | 0x1023: 0x2000 | deva- ctrl-4dwave.so | X86 | |
| Trident | 4DWave-NX | 0x1023: 0x2001 | deva- ctrl-4dwave.so | X86 | |
| TVIA | CyberPro 5 TVIA5050 | 0x10ea: 0x5050 | deva-ctrl- cyberpro5.so | X86 | |
| TVIA | CyberPro 5 TVIA5250 | 0x10ea: 0x5250 | deva-ctrl- cyberpro5.so | X86 | |
| TVIA | CyberPro 5 TVIA5355 | 0x10ea: 0x5350 | deva-ctrl- cyberpro5.so | X86 | |
| VIA Technologies | Via 82c686A PCI Southbridge | 0x1106: 0x3058 | deva-ctrl- via686.so | X86 | |
| Yamaha | YMF724 | 0x1073: 0x0004 | deva-ctrl- ymfdfs1.so | X86 | |
| Yamaha | YMF724F | 0x1073: 0x000d | deva-ctrl- ymfdfs1.so | X86 | |
| Yamaha | YMF740 | 0x1073: 0x000a | deva-ctrl- ymfdfs1.so | X86 | |
| Yamaha | YMF740C | 0x1073: 0x000c | deva-ctrl- ymfdfs1.so | X86 | |
| Yamaha | YMF744 | 0x1073: 0x0010 | deva-ctrl- ymfdfs1.so | X86 | |
| Yamaha | YMF754 | 0x1073: 0x0012 | deva-ctrl- ymfdfs1.so | X86 | |

| | | | | | |
|-------|---------------------|-----|--------------|-----------------------------|---|
| Canon | Canon compatible | N/A | phs-to-bjc | ARM, MIPS, PPC, SH4, X86 | |
| Epson | Epson compatible | N/A | phs-to-escp2 | ARM, MIPS, PPC, SH4, X86 | |
| Epson | Stylus C20 | N/A | phs-to-ijc | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. Not available for mipsbe processors |
| Epson | Stylus C40 | N/A | phs-to-ijc | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. Not available for mipsbe processors |
| Epson | Stylus C42 | N/A | phs-to-ijc | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. Not available for mipsbe processors |

| | | | | | | |
|-------|------------------|-----|-----------|--------------------------|---|--|
| Epson | Stylus C60 | N/A | phs-to-ij | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. Not available for mipsbe processors | |
| Epson | Stylus C70 | N/A | phs-to-ij | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. Not available for mipsbe processors | |
| Epson | Stylus C80 | N/A | phs-to-ij | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. Not available for mipsbe processors | |
| Epson | Stylus COLOR 400 | N/A | phs-to-ij | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. Not available for mipsbe processors | |
| Epson | Stylus COLOR 440 | N/A | phs-to-ij | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. Not available for mipsbe processors | |
| Epson | Stylus COLOR 480 | N/A | phs-to-ij | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. Not available for mipsbe processors | |
| Epson | Stylus COLOR 500 | N/A | phs-to-ij | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. Not available for mipsbe processors | |
| Epson | Stylus COLOR 580 | N/A | phs-to-ij | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. Not available for mipsbe processors | |
| Epson | Stylus COLOR 600 | N/A | phs-to-ij | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. Not available for mipsbe processors | |
| Epson | Stylus COLOR 640 | N/A | phs-to-ij | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. Not available for mipsbe processors | |
| Epson | Stylus COLOR 670 | N/A | phs-to-ij | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. Not available | |

| | | | | | |
|-------|------------------|-----|------------|--------------------------|---|
| | | | | | for mipsbe processors |
| Epson | Stylus COLOR 680 | N/A | phs-to-ijc | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. Not available for mipsbe processors |
| Epson | Stylus COLOR 740 | N/A | phs-to-ijc | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. Not available for mipsbe processors |
| Epson | Stylus COLOR 750 | N/A | phs-to-ijc | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. Not available for mipsbe processors |
| Epson | Stylus COLOR 760 | N/A | phs-to-ijc | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. Not available for mipsbe processors |
| Epson | Stylus COLOR 777 | N/A | phs-to-ijc | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. Not available for mipsbe processors |
| Epson | Stylus COLOR 800 | N/A | phs-to-ijc | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. Not available for mipsbe processors |
| Epson | Stylus COLOR 850 | N/A | phs-to-ijc | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. Not available for mipsbe processors |
| Epson | Stylus COLOR 860 | N/A | phs-to-ijc | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. Not available for mipsbe processors |
| Epson | Stylus COLOR 870 | N/A | phs-to-ijc | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. Not available for mipsbe processors |
| Epson | Stylus COLOR 880 | N/A | phs-to-ijc | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. Not available for mipsbe processors |
| Epson | Stylus COLOR 900 | N/A | phs-to-ijc | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. |

| | | | | | | |
|-----------------|-------------------------------|-----|------------|--------------------------|---|--|
| | | | | | Not available for mipsbe processors | |
| Epson | Stylus COLOR 980 | N/A | phs-to-ijc | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. Not available for mipsbe processors | |
| Epson | Stylus COLOR 1160 | N/A | phs-to-ijc | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. Not available for mipsbe processors | |
| Epson | Stylus COLOR 1270 | N/A | phs-to-ijc | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. Not available for mipsbe processors | |
| Epson | Stylus Photo 790 | N/A | phs-to-ijc | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. Not available for mipsbe processors | |
| Epson | Stylus Photo 820 | N/A | phs-to-ijc | ARM, MIPS, PPC, SH4, X86 | 6.2.1 Patch B Supplemental. Not available for mipsbe processors | |
| Generic | Post-script compatible | N/A | phs-to-ps | ARM, MIPS, PPC, SH4, X86 | | |
| Generic | Generic USB Printer | N/A | devu-prn | ARM, MIPS, PPC, X86 | There is no USB printer support for Mipsbe (big endian) target | |
| Hewlett-Packard | HP compatible | N/A | phs-to-pcl | ARM, MIPS, PPC, SH4, X86 | | |
| Lexmark | Lexmark 3000 Color Jetprinter | N/A | phs-to-ps | ARM, MIPS, PPC, SH4, X86 | | |
| Lexmark | Lexmark J110 | N/A | phs-to-ps | ARM, MIPS, PPC, SH4, X86 | | |
| Lexmark | Optra Color 45 | N/A | phs-to-ps | ARM, MIPS, PPC, SH4, X86 | | |
| Lexmark | Optra E312(L) Models | N/A | phs-to-ps | ARM, MIPS, PPC, SH4, X86 | | |
| Lexmark | Optra S1255 | N/A | phs-to-ps | ARM, MIPS, PPC, SH4, X86 | | |
| Lexmark | Optra S2455 | N/A | phs-to-ps | ARM, MIPS, PPC, SH4, X86 | | |

PC Card

| Vendor | Model | Vendor:DeviceID | Drivers | Supported CPU Note | |
|-------------------|-------------|-----------------|-------------|--------------------|--|
| Cirrus | PD6710 | N/A | devp-pccard | X86 | |
| Cirrus | PD672x | N/A | devp-pccard | X86 | |
| Cirrus | PD6729 | 1013h: 1100h | devp-pccard | X86 | |
| Cirrus | PD6730 | N/A | devp-pccard | X86 | |
| Cirrus | PD6832 | 1013h: 1110h | devp-pccard | X86 | |
| Intel | 82365A | N/A | devp-pccard | X86 | |
| Intel | 82365B | N/A | devp-pccard | X86 | |
| Intel | 82635DF | N/A | devp-pccard | X86 | |
| O2 Micro | OZ6729 | 1217h: 6729h | devp-pccard | X86 | |
| O2 Micro | OZ6730 | 1217h: 673ah | devp-pccard | X86 | |
| O2 Micro | OZ6832 | 1217h: 6832h | devp-pccard | X86 | |
| O2 Micro | OZ6836 | 1217h: 6836h | devp-pccard | X86 | |
| O2 Micro | OZ6933 | 1217h: 6933h | devp-pccard | X86 | |
| O2 Micro | OZ6812 | 1217h: 6872h | devp-pccard | X86 | |
| O2 Micro | OZ6912 | 1217h: 6972h | devp-pccard | X86 | |
| Ricoh | RF5C296/396 | N/A | devp-pccard | X86 | |
| Ricoh | RL5C465 | 1180h: 0465h | devp-pccard | X86 | |
| Ricoh | RL5C466 | 1180h: 0466h | devp-pccard | X86 | |
| Ricoh | RL5C475 | 1180h: 0475h | devp-pccard | X86 | |
| Ricoh | RL5C476 | 1180h: 0476h | devp-pccard | X86 | |
| Ricoh | RL5C478 | 1180h: 0478h | devp-pccard | X86 | |
| Texas Instruments | TI1130 | 104ch: ac12h | devp-pccard | X86 | |
| Texas Instruments | TI1131 | 104ch: ac15h | devp-pccard | X86 | |
| Texas Instruments | TI1210 | 104ch: ac1ah | devp-pccard | X86 | |
| Texas Instruments | TI1211 | 104ch: ac1eh | devp-pccard | X86 | |
| Texas Instruments | TI1220 | 104ch: ac17h | devp-pccard | X86 | |
| Texas Instruments | TI1221 | 104ch: ac19h | devp-pccard | X86 | |
| Texas Instruments | TI1225 | 104ch: ac1ch | devp-pccard | X86 | |
| Texas Instruments | TI1250A | 104ch: ac16h | devp-pccard | X86 | |
| Texas Instruments | TI1251A | 104ch: ac1dh | devp-pccard | X86 | |
| Texas Instruments | TI1251B, | 104ch: ac1fh | devp-pccard | X86 | |
| Texas Instruments | TI1410 | 104ch: ac50h | devp-pccard | X86 | |
| Texas Instruments | TI1420 | 104ch: ac51h | devp-pccard | X86 | |
| Texas Instruments | TI1450 | 104ch: ac1bh | devp-pccard | X86 | |
| Texas Instruments | TI1510 | 104ch: ac56h | devp-pccard | X86 | |
| Texas Instruments | TI1520 | N/A | devp-pccard | X86 | |
| Texas Instruments | TI4450 | 104ch: ac40h | devp-pccard | X86 | |
| Texas Instruments | TI4451 | 104ch: ac42h | devp-pccard | X86 | |
| Texas Instruments | TI4510 | 104ch: ac44h | devp-pccard | X86 | |
| Toshiba | TOPIC-95A | 1179h: 0603h | devp-pccard | X86 | |
| Toshiba | TOPIC-95B | 1179h: 060ah | devp-pccard | X86 | |
| Toshiba | TOPIC-97 | 1179h: 060fh | devp-pccard | X86 | |
| Vadem | VG468/9 | N/A | devp-pccard | X86 | |
| VLSI | 82C146 | N/A | devp-pccard | X86 | |

| Vendor | Model | Vendor:DeviceID | Drivers | Supported CPU Note | | |
|-----------|--|-----------------|-------------------|---------------------|---|--|
| Broadcom | Broadcom MIPS BCM12500 DUART Device Driver | N/A | devc-serbcm1250 | MIPS | Please contact Sales for availability of BroadcomBCM1250 (MIPS64) | |
| Freescale | PPC 80x serial port | N/A | devc-serppc800 | PPC | | |
| Freescale | PPC403 built-in serial port | N/A | devc-ser403 | PPC | | |
| Freescale | Redbox Device Driver | N/A | devc-redbox | PPC | Please contact Sales for availability of RPX-Lite/HIOX BSP | |
| Freescale | 8260 Serial device driver | N/A | devc-ser8260 | PPC | Please contact Sales for availability of ADS826x BSP | |
| Generic | Generic | N/A | devc-ser8250 | MIPS, PPC, SH4, X86 | 8250 with 16550/14450 compatible UART | |
| Generic | 2681 serial port | N/A | devc-ser2681 | MIPS, PPC, X86 | | |
| Generic | Console | N/A | devc-con | X86 | | |
| Generic | MIPS DSIU serial port | N/A | devc-serdsiu | MIPS | Only for mipsle | |
| Generic | Parallel Port | N/A | devc-par | X86 | | |
| Generic | Terminal | N/A | devc-pty | X86 | | |
| Generic | Primecell Device Driver | N/A | devc-serprimecell | ARM | | |
| Generic | PXA250 Device Driver | N/A | devc-serpxa250 | ARM | | |
| Generic | SA1100 Device Driver | N/A | devc-sersa1100 | ARM | | |
| Generic | SCI/SCIF Device Driver | N/A | devc-sersci | SH4 | | |
| Generic | MIPS AU1000 Serial Device Driver | N/A | devc-serau100 | MIPS | Available for mipsle only. Please contact Sales for availability | |
| Generic | GT64260 Device Driver | N/A | devc-sergt64260 | PPC | Please contact Sales for availability of Discovery BSP | |
| Generic | MC9328MX1 Device Driver | N/A | devc-sermx1 | ARM | Please contact Sales for availability of Xilinx/Vizteck 2 Pro | |

| | | | | | | |
|---------------|---|--|----------------|----------------------|--|--|
| Generic | OMAP Serial Device Driver | N/A | devc-seromap | ARM | Please contact Sales for availability of OMAP 1610 | |
| Generic | S3C2400 Device Driver | N/A | devc-ser3c2400 | ARM | Please contact Sales for availability of Samsung 3C2400 | |
| Hitachi | Hitachi Serial Protocol Interface (HSPI) driver | N/A | devc-hspi | SH4 | Please contact Sales for availability of Biscayne BSP | |
| Hitachi | Amanda Device Driver | N/A | devc-seramanda | SH4 | Please contact Sales for availability of BigSur / Amanda BSP | |
| IBM | PPC 80x serial port | N/A | devc-serppc800 | PPC | | |
| Sealevel | Asynchronous RS-232 Serial I/O adapter | N/A | devc-ser8250 | X86 | PCMCIA card | |
| Zilog | Zilog SCC serial chip | N/A | devc-serzzsc | MIPS, PPC, X86 | | |
| Vendor | Model | Vendor:DeviceID | Drivers | Supported CPU | | |

Keyboard and Mouse

| Vendor | Model | Vendor:DeviceID | Drivers | Supported CPU Note | |
|---------------|----------------------------------|--|-------------------------|---------------------------|--|
| Belkin | Belkin USB Keyboard | N/A | devu-kbd, devh-usb.so | ARM, MIPS, PPC, SH4, X86 | |
| Generic | Generic Keyboard | N/A | devi-hirun, devi-hid | ARM, MIPS, PPC, SH4, X86 | |
| Generic | Generic Mouse (ps2/serial) | N/A | devi-hirun, devi-hid | ARM, MIPS, PPC, SH4, X86 | |
| Generic | SA1111 input (ps2) | N/A | devi-sa1111 | ARM | |
| Generic | Primecell input (ps2) | N/A | devi-primecell | ARM | |
| Generic | P1100 input | N/A | devi-p1100 | ARM | |
| Generic | Tahoe input (ps2) | N/A | devi-Tahoe | SH4 | |
| Generic | Sengine input (ps2/serial) | N/A | devi-sengine | SH4 | |
| Generic | Generic USB Keyboard | N/A | devu-kbd, devh-usb.so | ARM, MIPS, PPC, SH4, X86 | |
| Generic | USB keyboard for Amanda (Sh4 le) | N/A | devu-kbd-amanda | SH4 | |
| Generic | Generic USB Mouse | N/A | devu-mouse, devh-usb.so | ARM, MIPS, PPC, SH4, X86 | |

| | | | | | |
|-----------|--------------------------------|-----------|-------------------------|--------------------------|--|
| IBM | IBM USB 3 Button Mouse | 04B3:3103 | devu-mouse | ARM, MIPS, PPC, SH4, X86 | |
| Logitech | Logitech 3 Button Mouse | N/A | devu-mouse, devh-usb.so | ARM, MIPS, PPC, SH4, X86 | |
| Logitech | Logitech USB Wheel Mouse | N/A | devu-mouse, devh-usb.so | ARM, MIPS, PPC, SH4, X86 | |
| Logitech | Logitech Optical Wheel Mouse | 046D:C00C | devu-mouse | ARM, MIPS, PPC, SH4, X86 | |
| Microsoft | MS Natural® Keyboard Pro | N/A | devu-kbddevh-usb.so | ARM, MIPS, PPC, SH4, X86 | |
| Microsoft | MS IntelliMouse™ | N/A | devu-mouse, devh-usb.so | ARM, MIPS, PPC, SH4, X86 | |
| Microsoft | MS IntelliMouse™ Optical | N/A | devu-mouse, devh-usb.so | ARM, MIPS, PPC, SH4, X86 | |
| Microsoft | MS Natural® Multimedia® | N/A | ps2_ser | ARM, MIPS, PPC, X86 | |
| USB | USB keyboard for Amanda (Shle) | N/A | devu-mouse-amanda | SH4 | |

Video

| Vendor | Model | Vendor:DeviceID | Drivers | Supported CPU Note | |
|--------|---------------------------------|--|-----------------|--------------------|--|
| 3dfx | Voodoo Banshee | 0x121A: 0x0003 | devg-banshee.so | X86 | |
| 3dfx | Voodoo 3 | 0x121A: 0x0004, 0x0005 | devg-banshee.so | X86 | |
| 3dfx | Voodoo 4/5 | 0x121A: 0x0009 | devg-banshee.so | X86 | |
| ATI | Mach64 CT | 0x1002: 0x4354 | devg-mach64.so | X86 | |
| ATI | Mach64 CX | 0x1002: 0x4358 | devg-mach64.so | X86 | |
| ATI | Mach64 ET | 0x1002: 0x4554 | devg-mach64.so | X86 | |
| ATI | Mach64 GX | 0x1002: 0x4758 | devg-mach64.so | X86 | |
| ATI | Mach64 VT | 0x1002: 0x5654 | devg-mach64.so | X86 | |
| ATI | Mach64 VTB | 0x1002: 0x5655 | devg-mach64.so | X86 | |
| ATI | Rage IIC | 0x1002: 0x5656 | devg-rage.so | X86 | |
| ATI | Radeon | 0x1002: 0x5144 | devg-radeon.so | X86 | |
| ATI | Radeon 7200 | 0x1002: 0x5145, 0x5146, 0x5147 | devg-radeon.so | X86 | |
| ATI | Radeon Mobility M6 | 0x1002: 0x4c59, 0x4c5A | devg-radeon.so | X86 | |
| ATI | Radeon Mobility M7 | 0x1002: 0x4c57, 0x4c58 | devg-radeon.so | X86 | |
| ATI | Radeon 7000/VE | 0x1002: 0x5159, 0x515A | devg-radeon.so | X86 | |
| ATI | Radeon 7500 | 0x1002: 0x5157, 0x5158 | devg-radeon.so | X86 | |
| ATI | Radeon 8500 | 0x1002: 0x514C, 0x514D, 0x514E, 0x514F | devg-radeon.so | X86 | |
| ATI | Radeon 8500 All In Wonder (AIW) | 0x1002: 0x4242 | devg-radeon.so | X86 | |

| | | | | | |
|-----|--------------------------------|---|-------------------------|----------------|--|
| ATI | Radeon 9000 | 0x1002: 0x4964, 0x4965, 0x4966, 0x4967 | devg-radeon.so | X86 | |
| ATI | Radeon 9700 | 0x1002: 0x4E44, 0x4E45, 0x4E46, 0x4E47 | devg-radeon.so | X86 | |
| ATI | 3D Rage IIC AGP | 0x1002: 0x4757, 0x475A | devg-rage.so | X86 | |
| ATI | 3D Rage Mobility M/M1/P | 0x1002: 0x4C4D, 0x4C52 | devg-rage.so | X86 | |
| ATI | 3D Rage ProPCI | 0x1002: 0x4749, 0x4750, 0x4751 | devg-rage.so | X86 | |
| ATI | 3D Rage Pro AGP | 0x1002: 0x4742, 0x4744 | devg-rage.so | X86 | |
| ATI | 3D Rage LT-Pro | 0x1002: 0x4C42, 0x4C47, 0x4C49, 0x4C50 | devg-rage.so | X86 | |
| ATI | 3D Rage II+ GTB | 0x1002: 0x4755 | devg-rage.so | X86 | |
| ATI | 3D Rage IIC PCI | 0x1002: 0x4756, 0x4765 | devg-rage.so | X86 | |
| ATI | Rage128 GL | 0x1002: 0x5245, 0x5246, 0x534B, 0x534C, 0x534D | devg- ati_rage128.so | MIPS, PPC, X86 | |
| ATI | Rage 128 VR | 0x1002: 0x524B, 0x524C, 0x5345, 0x5346, 0x5347 | devg- ati_rage128.so | MIPS, PPC, X86 | |
| ATI | Rage128 Pro GL | 0x1002: 0x5041, 0x5042, 0x5043, 0x5044, 0x5045, 0x5046 | devg- ati_rage128.so | MIPS, PPC, X86 | |
| ATI | Rage 128 Pro VR | 0x1002: 0x5047, 0x5048, 0x5049, 0x504A, 0x504B, 0x504C, 0x504D, 0x504E, 0x504F, 0x5050, 0x5051, 0x5052, 0x5053, 0x5054, 0x5055, 0x5056, 0x5057, 0x5058 | devg- ati_rage128.so | MIPS, PPC, X86 | |
| ATI | Rage 128 Expert Pro 2000 | 0x1002: 0x5446 | devg- ati_rage128.so | MIPS, PPC, X86 | |
| ATI | Rage 128 Mobility M3 | 0x1002: 0x4C45, 0x4C46 | devg- ati_rage128.so | MIPS, PPC, X86 | |
| ATI | Rage 128 Mobility M4 | 0x1002: 0x4D46 | devg- ati_rage128.so | MIPS, PPC, X86 | |
| ATI | Radeon 9800 | 0x1002: 0x4E48, 0x4148, 0x4E49 | devg-radeon.so | X86 | |
| ATI | Radeon 9800 XT | 0x1002: 0x4E4A | devg-radeon.so | X86 | |
| ATI | Radeon Mobility M9 | 0x1002: 0x4C64, 0x4C65, 0x4c66, 0x4C67 | devg-radeon.so | X86 | |

| | | | | | |
|----------------------|----------------------|--|------------------|--------------------------|--|
| ATI | Radeon Mobility 9200 | 0x1002: 0x5c61, 0x5c63 | devg-radeon.so | X86 | |
| ATI | Radeon 9600 | 0x1002: 0x4150, 0x4151, 0x4e50, 0x4e52 | devg-radeon.so | X86 | |
| ATI | Radeon 9700 Pro | 0x1002: 0x4145, 0x4146, 0x4147 | devg-radeon.so | X86 | |
| ATI | Radeon 9500 | 0x1002: 0x4149, 0x4144 | devg-radeon.so | X86 | |
| ATI | Radeon 9600 XT | 0x1002: 0x4152 | devg-radeon.so | X86 | |
| ATI | Radeon 9200 | 0x1002: 0x5960, 0x5961, 0x5964 | devg-radeon.so | X86 | |
| ATI | Radeon 9100 | 0x1002: 0x514D | devg-radeon.so | X86 | |
| ATI | Radeon X300 | 0x1002: 0x5b60 | devg-radeon.so | PPC, X86 | |
| ATI | Radeon X600 | 0x1002: 0x3e50 | devg-radeon.so | PPC, X86 | |
| ATI | Rage XL | 0x1002: 0x4752 | devg-radeon.so | X86 | |
| Chips & Technologies | CT65550 | 0x102C: 0x00E0 | devg-chips.so | ARM, MIPS, PPC, SH4, X86 | |
| Chips & Technologies | CT65550 (ISA) | N/A | devg-chips.so | X86 | |
| Chips & Technologies | CT65554 | 0x102C: 0x00E4 | devg-chips.so | ARM, MIPS, PPC, SH4, X86 | |
| Chips & Technologies | CT65555 | 0x102C: 0x00E5 | devg-chips.so | ARM, MIPS, PPC, SH4, X86 | |
| Chips & Technologies | CT69000 | 0x102C: 0x00C0 | devg-chips.so | ARM, MIPS, PPC, SH4, X86 | |
| Chips & Technologies | CT69030 | 0x102C: 0x0C30 | devg-chips.so | ARM, MIPS, PPC, SH4, X86 | |
| Fujitsu | Coral-P | 0x10CF; 0x2019 | devg-coral.so | ARM, PPC, SH4, X86 | |
| Fujitsu | Coral-B | | devg-coral.so | ARM, PPC, SH4, X86 | |
| Fujitsu | Orchid | 0x10b5:0x9080 | devg-orchid.so | PPC, SH4, X86 | |
| Fujitsu | Coral-PA | 0x10CF; 0x201e | devg-coral.so | ARM, PPC, SH4, X86 | |
| Generic | IBM vga compatible | N/A | devg-vga.so | X86 | |
| Generic | VESA 1.2 cards | N/A | devg-svga.so | X86 | |
| Generic | VESA 2.0 cards | N/A | devg-vesabios.so | X86 | |
| Hitachi | Q2SD | N/A | devg-q2sd.so | SH4 | |
| Hitachi | Amanda | N/A | devg-amanda.so | SH4 | |
| Intel | 82810 DC100 | 0x8086: 0x7123 | devg-i810.so | X86 | |
| Intel | 82810E | 0x8086: 0x7125 | devg-i810.so | X86 | |
| Intel | PXA250 | N/A | devg-pxa250.so | ARM | |
| Intel | SA1110 | N/A | devg-sa1110.so | ARM | |
| Intel | 82830 | 0x8086; 0x3577 | devg-i830.so | X86 | |
| Intel | 82852 | 0x8086; 0x3582 | devg-i830.so | X86 | |
| Intel | 82855 | 0x8086; 0x3582 | devg-i830.so | X86 | |
| Intel | 82845 | 0x8086; 0x2562 | devg-i830.so | X86 | |
| Intel | 82865 | 0x8086; 0x2572 | devg-i830.so | X86 | |
| Intel | 82915 | 0x8086; 0x2582, 0x2592 | devg-i830.so | X86 | |

| | | | | | |
|--------------------------------------|-----------------------------------|--|------------------|------------------------|--|
| Intel | 82945 | 0x8086; 0x2772, 0x27a2 | devg-i830.so | X86 | |
| Matrox | G100 AGP | 0x102B: 0x1001 | devg-matrox.so | X86 | |
| Matrox | G200 PCI | 0x102B: 0x0520 | devg-matroxg.so | X86 | |
| Matrox | G200 AGP | 0x102B: 0x0521 | devg-matroxg.so | X86 | |
| Matrox | G400/G450 AGP | 0x102B: 0x0525 | devg-matroxg.so | X86 | |
| Matrox | G550 AGP | 0x102B: 0x2527 | devg-matroxg.so | X86 | |
| Matrox | Millenium PCI | 0x102B: 0x0519 | devg-matrox.so | X86 | |
| Matrox | Millenium II | 0x102B: 0x051B, 0x051F | devg-matrox.so | X86 | |
| Matrox | Mystique | 0x102B: 0x051A | devg-matrox.so | X86 | |
| Mediaq Inc. | M200 | 0x4D51: 0x200 | devg-mq200.so | MIPS, PPC, SH4, X86 | |
| National Semiconductor | Geode Dorado | 0x100B: 0x0504 | devg-geode.so | X86 | |
| National Semiconductor | Geode GX1 | N/A | devg-geode.so | X86 | |
| National Semiconductor | MediaGX | 0x1078: 0x0104 | devg-geode.so | X86 | |
| National Semiconductor | Geode GXLV | N/A | devg-geode.so | X86 | |
| NEC | RavinE | 0x1033; 0x0111 | devg-ravin.so | MIPS, PPC, X86 | |
| NeoMagic Corporation | MagicGraph128 XD | 0x10C8: 0x0004 | devg-neomagic.so | X86 | |
| NeoMagic Corporation | MagicMedia128 ZV | 0x10C8: 0x0003 | devg-neomagic.so | X86 | |
| NeoMagic Corporation | MagicMedia128 ZV+ | 0x10C8: 0x0083 | devg-neomagic.so | X86 | |
| NeoMagic Corporation | MagicMedia256 AV | 0x10C8: 0x0005 | devg-neomagic.so | X86 | |
| NeoMagic Corporation | MagicMedia256 AV+ | 0x10C8: 0x0025 | devg-neomagic.so | X86 | |
| NeoMagic Corporation | MagicMedia256 XL+ | 0x10C8: 0x0016 | devg-neomagic.so | X86 | |
| NeoMagic Corporation | MagicMedia256 ZX | 0x10C8: 0x0006 | devg-neomagic.so | X86 | |
| nVidia | GeForce | 0x10DE: 0x0102, 0x0110, 0x0111, 0x0112, 0x0113 | devg-tnt.so | X86 | |
| nVidia | GeForce SDR | 0x10DE: 0x0100 | devg-tnt.so | X86 | |
| nVidia | GeForce DDR | 0x10DE: 0x0101 | devg-tnt.so | X86 | |
| nVidia | GeForce Quadro | 0x10DE: 0x0103 | devg-tnt.so | X86 | |
| nVidia | GeForce Quadro MX | 0x10DE: 0x0113 | devg-tnt.so | X86 | |
| nVidia | GeForce2 GO | 0x10DE: 0x0112 | devg-tnt.so | X86 | |
| nVidia | GeForce2 | 0x10DE: 0x0153 | devg-tnt.so | X86 | |
| nVidia | GeForce2 GTS | 0x10DE: 0x0150, 0x0151, 0x0152 | devg-tnt.so | X86 | |
| nVidia | Riva 128 | 0x12D2: 0x0018, 0x0019 | devg-tnt.so | X86 | |
| nVidia | Riva TNT | 0x10DE: 0x0020 | devg-tnt.so | X86 | |

| | | | | | |
|----------------------|-------------------------------|--|-------------------|--------------------------|--|
| nVidia | Riva TNT2 | 0x10DE: 0x0028, 0x0029, 0x002A, 0x002B, 0x002C, 0x002D, 0x002E, 0x002F, 0x00A0 | devg-tnt.so | X86 | |
| S3 | Savage2000 (Integrated) | 0x5333: 0x8A25 | devg-s3_savage.so | X86 | |
| S3 | Savage4(Savage 3D) | 0x5333: 0x8A22 | devg-s3_savage.so | X86 | |
| S3 | Trio 64 | 0x5333: 0x8811 | devg-s3.so | X86 | |
| S3 | Trio 64V2 | 0x5333: 0x8901 | devg-s3.so | X86 | |
| S3 | ViRGE | 0x5333: 0x5631 | devg-s3.so | X86 | |
| S3 | ViRGE VX | 0x5333: 0x883D | devg-s3.so | X86 | |
| S3 | ViRGE GX | 0x5333: 0x8A01 | devg-s3.so | X86 | |
| S3 | ViRGE MX | 0x5333: 0x8c01 | devg-s3.so | X86 | |
| S3 | Vision 864 | 0x5333: 0x88C0, 0x88C1 | devg-s3.so | X86 | |
| S3 | Vision 868 | 0x5333: 0x8880 | devg-s3.so | X86 | |
| S3 | Vision 968 | 0x5333: 0x88F0 | devg-s3.so | X86 | |
| S3 | Savage Twister/ Twister T | 0x5333: 0x8D01 | devg-s3_savage.so | X86 | |
| SIS | 630 | 0x1039; 0x6300 | devg-sis630.so | X86 | |
| SIS | 300 | 0x1039; 0x0300 | devg-sis630.so | X86 | |
| SMI (Silicon Motion) | SM501 Voyager GX | 0x126F; 0x0501 | devg-smi5xx.so | ARM, MIPS, PPC, SH4, X86 | |
| SMI (Silicon Motion) | SM722 | 0x126F; 0x0720 | devg-smi7xx.so | ARM, MIPS, PPC, SH4, X86 | |
| SMI (Silicon Motion) | SM731 | 0x126F; 0x0730 | devg-smi7xx.so | ARM, MIPS, PPC, SH4, X86 | |
| SMI (Silicon Motion) | SM712 | 0x126F; 0x0712 | devg-smi7xx.so | ARM, MIPS, PPC, SH4, X86 | |
| ST Microelectronics | STPC Consumer | 0x104A: 0x0209 | devg-stpc.so | X86 | |
| ST Microelectronics | STPC Consumer II | 0x104A: 0x020A | devg-stpc.so | X86 | |
| TVIA | CyberPro 50xx | 0x10EA: 0x5000 | devg-igs5000.so | MIPS, X86 | |
| TVIA | CyberPro 52xx | 0x10EA: 0x5200 | devg-tvia.so | MIPS, SH4, X86 | |
| TVIA | CyberPro 53xx | 0x10EA: 0x5300 | devg-tvia.so | MIPS, SH4, X86 | |

Touchscreen

| Vendor | Model | Vendor: DeviceID | Drivers | Supported CPU Note | |
|---------|--------------------|----------------------------------|--------------------------|--------------------------|--------------------------------------|
| Carroll | Carrol touch input | N/A | devi-carrol | ARM, MIPS, PPC, SH4, X86 | Serial Dyna Dyna touch input |
| | N/A | devi-dyna | ARM, MIPS, PPC, SH4, X86 | Serial | Elographics Elographics input |
| | N/A | devi-elo | ARM, MIPS, PPC, SH4, X86 | Serial | Generic Ucb1300 input (SA1110) |
| | N/A | devi-ucb1300 | ARM | Serial | Generic Ucb1400 input (PXA250TMDP) |
| | N/A | devi-ucb1400 | ARM | Serial | Gunze Gunze AHL input |
| | N/A | devi-ahl | ARM, MIPS, PPC, SH4, X86 | Serial | Microtouch Microtouch input |
| | N/A | devi-microtouch | ARM, MIPS, PPC, SH4, X86 | Serial, PS/2, USB | RPXlite Rpxlite input |
| | N/A | devi-rpxlite | PPC | Serial | |

Network

| Vendor | Model | Vendor:DeviceID | Drivers | Supported CPU Note | | |
|--------|--------------|-------------------|---------------|--------------------------|---------------------|--|
| 3com | 3C575B | 10b7: 5157 | devn-el900.so | ARM, PPC, X86 | Cardbus | |
| 3com | 3CCFE575CT | 10b7: 5257 | devn-el900.so | ARM, PPC, X86 | Cardbus | |
| 3com | 3CCFE656 | 10b7: 6560 | devn-el900.so | ARM, PPC, X86 | Cardbus | |
| 3com | 3CCFEM656 | 10b7: 6562 | devn-el900.so | ARM, PPC, X86 | Cardbus | |
| 3com | 3CCFEM656 | 10b7: 656x | devn-el900.so | ARM, PPC, X86 | Cardbus | |
| 3com | 3C3FEM656C | N/A | devn-el900.so | ARM, PPC, X86 | Cardbus | |
| 3com | 3C589 | 0101: 0589 | devn-el589.so | ARM, MIPS, PPC, X86 | PCMCIA | |
| 3com | 3C900-TPO | 10b7: 9000 | devn-el900.so | ARM, MIPS, PPC, X86 | PCI | |
| 3com | 3C905-Tx | 10b7: 9050 | devn-el900.so | ARM, MIPS, PPC, X86 | PCI | |
| 3com | 3C905B-Tx | 10b7: 9055 | devn-el900.so | ARM, MIPS, PPC, X86 | PCI | |
| 3com | 3C905B-COMBO | 10b7: 9058 | devn-el900.so | ARM, MIPS, PPC, X86 | PCI | |
| 3com | 3C905C-Tx | 10b7: 9200 | devn-el900.so | ARM, MIPS, PPC, X86 | PCI | |
| 3com | 3C900-COMBO | 10b7: 9001 | devn-el900.so | ARM, MIPS, PPC, X86 | PCI | |
| 3com | 3C905-T4 | 10b7: 9051 | devn-el900.so | ARM, MIPS, PPC, X86 | PCI | |
| 3com | 3C905B-T4 | 10b7: 9056 | devn-el900.so | ARM, MIPS, PPC, X86 | PCI | |
| 3com | 3C900B-TPO | 10b7: 9004 | devn-el900.so | ARM, MIPS, PPC, X86 | PCI | |
| 3com | 3C900B-COMBO | 10b7: 9005 | devn-el900.so | ARM, MIPS, PPC, X86 | PCI | |
| 3com | 3C900B-TPC | 10b7: 9006 | devn-el900.so | ARM, MIPS, PPC, X86 | PCI | |
| 3com | 3C900B-FL | 10b7: 900a | devn-el900.so | ARM, MIPS, PPC, X86 | PCI | |
| 3com | 3C905B-Fx | 10b7: 905a | devn-el900.so | ARM, MIPS, PPC, X86 | PCI | |
| 3com | 3C980-Tx | 10b7: 9800 | devn-el900.so | ARM, MIPS, PPC, X86 | PCI | |
| 3com | 3C556 | 10b7: 6055 | devn-el900.so | ARM, MIPS, PPC, X86 | PCI | |
| 3com | 3C460 | N/A | devn.klsi.so | ARM, MIPS, PPC, X86 | USB | |
| 3com | Python-T | 0x10B7; 0x9805 | devn-el900.so | ARM, MIPS, PPC, SH4, X86 | 10/100baseTX NIC | |

| | | | | | | |
|--------------------------------|----------------|-------------------|-----------------|---------------------|--|--|
| AboCom Systems | FE2500 | 13d1: ab02 | devn-tulip.so | PPC, X86 | Cardbus | |
| Accton Technology | EN-1207D | 1113: 1211 | devn-rtl.so | ARM, MIPS, PPC, X86 | PCI | |
| ADMtek | AM181 | 1317: 0981 | devn-tulip.so | MIPS, PPC, X86 | PCI | |
| ADMtek | ADM983 | 1317: 0985 | devn-tulip.so | MIPS, PPC, X86 | PCI | |
| AMD | AM79C976 | 1022: 2000 | devn-pcnet.so | ARM, MIPS, PPC, X86 | PCI | |
| AMD | AM79C978 | 1022: 2001 | devn-pcnet.so | ARM, MIPS, PPC, X86 | PCI | |
| AMD | 79c960 | N/A | devn-pcnet.so | X86 | ISA | |
| AMD | 79c961 | N/A | devn-pcnet.so | ARM, X86 | ISA | |
| AMD | 79c965 | N/A | devn-pcnet.so | ARM, X86 | ISA | |
| AMD | AM79C970 | 1022: 2000 | devn-pcnet.so | ARM, MIPS, PPC, X86 | PCI | |
| AMD | AM79C971 | 1022: 2000 | devn-pcnet.so | ARM, MIPS, PPC, X86 | PCI | |
| AMD | AM79C972 | 1022: 2000 | devn-pcnet.so | ARM, MIPS, PPC, X86 | PCI | |
| AMD | AM79C973 | 1022: 2000 | devn-pcnet.so | ARM, MIPS, PPC, X86 | PCI | |
| AMD | AM79C975 | 1022: 2000 | devn-pcnet.so | ARM, MIPS, PPC, X86 | PCI | |
| Artesyn | Crystal 8900 | N/A | devn-artesyn.so | PPC | | |
| Broadcom | 5700 Gigabit | 0x14E4; 0x1644 | devn-tigon3.so | PPC, X86 | NetXtreme Gigabit Ethernet Controller | |
| Broadcom | 5702 Gigabit | 0x14E4; 0x1646 | devn-tigon3.so | PPC, X86 | NetXtreme Gigabit Ethernet Controller | |
| Broadcom | 5703 Gigabit | 0x14E4; 0x1647 | devn-tigon3.so | PPC, X86 | NetXtreme Gigabit Ethernet Controller | |
| Broadcom | 5701 Gigabit | 0x14E4; 0x1645 | devn-tigon3.so | PPC, X86 | NetXtreme Gigabit Ethernet Controller | |
| Broadcom | 5702FE Gigabit | 0x14E4; 0x164D | devn-tigon3.so | PPC, X86 | NetXtreme Fast Ethernet Controller | |
| Broadcom | 5702X Gigabit | 0x14E4; 0x16A6 | devn-tigon3.so | PPC, X86 | NetXtreme Gigabit Ethernet Controller | |
| Broadcom | 5703X Gigabit | 0x14E4; 0x16A7 | devn-tigon3.so | PPC, X86 | NetXtreme Gigabit Ethernet Controller | |

| | | | | | | |
|-------------------|-------------------|----------------|-------------------------|--------------------------|---|--|
| Cirrus | CS8900 | N/A | devn-crys8900 | X86 | ISA | |
| Cirrus | CS8920 | N/A | devn-crys8900 | X86 | ISA | |
| D-Link | DE-660 | 0149: 021b | devn-ne2000.so | ARM, MIPS, PPC, SH4, X86 | PCMCIA | |
| D-Link | DFE-530Tx+ | 1186: 1300 | devn-rtl.so | ARM, MIPS, PPC, X86 | PCI | |
| D-Link | DUBE100 (rev. A) | 0x1a00 | devn-asix.so | ARM, MIPS, PPC, X86 | USB (released 6.3.0 SP3) | |
| Davicom | DM9102 | 0x1282: 0x9102 | devn-dm9102.so | ARM, MIPS, PPC, SH4, X86 | | |
| Digital Equipment | DC21142/3 | 1011: 0019 | devn-tulip.so | PPC, X86 | Cardbus | |
| Digital Equipment | DC21142/3 | 1011: 0019 | devn-tulip.so | PPC, X86 | PCI | |
| Digital Equipment | DC21040 | 1011: 0002 | devn-tulip.so | MIPS, PPC, X86 | PCI | |
| Digital Equipment | KZPSA | 1011: 0008 | devn-tulip.so | MIPS, PPC, X86 | PCI | |
| Digital Equipment | DC21140 | 1011: 0009 | devn-tulip.so | MIPS, PPC, X86 | PCI | |
| Digital Equipment | DC21041 | 1011: 0014 | devn-tulip.so | MIPS, PPC, X86 | PCI | |
| Digital Equipment | DC21142/3/5 | 1011: 0019 | devn-tulip.so | MIPS, PPC, X86 | PCI | |
| Freescale | MPC8xx | N/A | devn-ne2000-800.so | PPC | NE2000 variant for PCMCIA interface on MPC8xx based systems | |
| Freescale | MPC8xx | N/A | devn-ppc860_mii-fads.so | PPC | 860 FADS 10/100 ethernet driver | |
| Freescale | MPC8xx | N/A | devn-ppc860_mii-cllf.so | PPC | 860 CLLF 10/100 ethernet driver | |
| Freescale | MPC826x | N/A | devn-ppc8260-ads.so | PPC | 8260 ads reference platform | |
| Freescale | MPC8xx | N/A | devn-ppc800-ads.so | PPC | ADS reference platform | |
| Freescale | MPC8xx | N/A | devn-ppc800-rpxlite.so | PPC | RPx-Lite | |
| Freescale | MPC8xx | N/A | devn-ppc800.so | PPC | | |
| Generic | Hubs | N/A | devu-ohci, devu-uhci | ARM, MIPS, PPC, SH4, X86 | | |
| IBM | Ppc405 | N/A | devn-ppc405.so | PPC | IBM PPCx05 on-chip ethernet | |
| Intel | 82551 | 8086: 1229 | devn-speedo.so | ARM, MIPS, PPC, X86 | PCI | |

| | | | | | | |
|-------|------------------------|--|----------------|-----------------------------|---|--|
| Intel | 82559ER | 8086: 1209 | devn-speedo.so | ARM, MIPS, PPC, X86 | PCI | |
| Intel | 82544EI/GC | 8086: 1008 | devn-i82544.so | PPC, X86 | PCI, Gigabit Ethernet | |
| Intel | 82544EI | 8086: 1009 | devn-i82544.so | PPC, X86 | PCI, Gigabit Ethernet | |
| Intel | 82544I | 8086: 100c | devn-i82544.so | PPC, X86 | PCI, Gigabit Ethernet | |
| Intel | 82544GC | 0x8086: 0x100c, 0x100d | devn-i82544.so | PPC, X86 | PCI, Gigabit Ethernet | |
| Intel | 82545EM | 8086: 100f | devn-i82544.so | PPC, X86 | PCI, Gigabit Ethernet | |
| Intel | 82545EM | 8086: 1011 | devn-i82544.so | PPC, X86 | PCI, Gigabit Ethernet | |
| Intel | 82546EB | 0x8086: 0x1010, 0x1012, 0x101d, 0x108a | devn-i82544.so | PPC, X86 | PCI, Gigabit Ethernet | |
| Intel | 82540EM | 0x8086: 0x100e, 0x1015 | devn-i82544.so | PPC, X86 | PCI, Gigabit Ethernet | |
| Intel | 3C509 TP/ COMBO/TPO | N/A | devn-el509.so | X86 | ISA | |
| Intel | 82559 | 0x8086: 0x1029 | devn-speedo.so | ARM, MIPS, PPC, SH4, X86 | | |
| Intel | 82801CAM (ICH3-M) | 0x8086: 0x1030 - 0x1038 | devn-speedo.so | ARM, MIPS, PPC, SH4, X86 | | |
| Intel | 82801DB (ICH4) | 0x8086: 0x1039 - 0x103E | devn-speedo.so | ARM, MIPS, PPC, SH4, X86 | | |
| Intel | 82562EZ | 0x8086: 0x1050 - 0x1055, 0x1059 | devn-speedo.so | ARM, MIPS, PPC, SH4, X86 | | |
| Intel | 82559B | 0x8086: 0x2459 | devn-speedo.so | ARM, MIPS, PPC, SH4, X86 | | |
| Intel | 82559C | 0x8086: 0x245D | devn-speedo.so | ARM, MIPS, PPC, SH4, X86 | | |
| Intel | 82541EI Gigabit | 0x8086: 0x1013, 0x1018, 0x1019 | devn-i82544.so | PPC, X86 | Gigabit Ethernet Controller (Copper) | |
| Intel | 82540EP Gigabit | 0x8086: 0x1016, 0x1017, 0x101E | devn-i82544.so | PPC, X86 | Gigabit Ethernet Controller | |
| Intel | 82545GM Gigabit | 0x8086: 0x1026, 0x1027, 0x1028 | devn-i82544.so | PPC, X86 | Gigabit Ethernet Controller | |

| | | | | | | |
|------------------------|-----------------------------|---|-----------------------|--------------------------|--|--|
| Intel | 82541GI Gigabit | 0x8086: 0x1075, 0x1076, 0x1077 | devn-i82544.so | PPC, X86 | Gigabit Ethernet Controller (Mobile) | |
| Intel | 82541ER Gigabit | 0x8086: 0x1078 | devn-i82544.so | PPC, X86 | Gigabit Ethernet Controller | |
| Intel | 82546GB Gigabit | 0x8086: 0x1079, 0x107A, 0x107B | devn-i82544.so | PPC, X86 | Dual Port Gigabit Ethernet Controller | |
| Intel | 82541PI Gigabit | 0x8086: 0x107c | devn-i82544.so | PPC, X86 | Gigabit Ethernet Controller | |
| Intel | 82573V | 0x8086: 0x108b | devn-i82544.so | PPC, X86 | PCI, Gigabit Ethernet (released 6.3.0 SP3) | |
| Intel | 82573E | 0x8086: 0x108c | devn-i82544.so | PPC, X86 | PCI, Gigabit Ethernet (release 6.3.0 SP3) | |
| Intel | 82573L | 0x8086: 0x109a | devn-i82544.so | PPC, X86 | PCI, Gigabit Ethernet (release 6.3.0 SP3) | |
| Intel | 82557 | 8086:1229 | devn-speedo.so | ARM, MIPS, PPC, X86 | PCI | |
| Intel | 82558 | 8086: 1229 | devn-speedo.so | ARM, MIPS, PPC, X86 | PCI | |
| Kawasaki | Kawasaki based USB Asapters | N/A | devn-klsi.so | ARM, MIPS, PPC, X86 | | |
| KTI | ET32/Px | 8e2e: 3000 | devn-ne2000.so | ARM, MIPS, PPC, SH4, X86 | PCI | |
| Lite-On Communications | NGMC169B | 11ad: 0002 | devn-tulip.so | MIPS, PPC, X86 | PCI | |
| Macronix | Mx98715/725 | 10d9: 0531 | devn-tulip.so | MIPS, PPC, X86 | PCI | |
| Marvell | Marvell | N/A | devn-gt64260.so | PPC | Marvell Discovery 6x260 ethernet driver | |
| National Semiconductor | DP83815/16 | 100b: 0020 | devn-ns83815.so | ARM, MIPS, PPC, X86 | PCI | |
| Netgear | EA101 | N/A | devn-klsi.so | ARM, MIPS, PPC, X86 | USB | |
| NetVin | beNV3000 | 4a14: 5000 | devn-ne2000.so | ARM, MIPS, PPC, SH4, X86 | PCI | |
| Novell | NE2000 compatible | N/A | devn-ne2000-sengin.so | SH4 | NE2000 variant driver for SHx based Solution | |

| | | | | | | |
|------------|---------------------------------|----------------|-----------------|--------------------------|--------------------------|--|
| Novell | NE2000 compatible | N/A | devn-ne2000.so | ARM, MIPS, PPC, SH4, X86 | ISA | |
| PNIC | 82C168 | N/A | devn-tulip.so | MIPS, PPC, X86 | PCI | |
| Powermatic | 832AE2803068 | 01f6: 1401 | devn-ne2000.so | ARM, MIPS, PPC, SH4, X86 | PCI | |
| Realtek | RT8139A/B/C | 10ec: 8139 | devn-rtl.so | ARM, MIPS, PPC, X86 | PCI | |
| Realtek | RT8139 A/B/C | 10ec: 8029 | devn-ne2000.so | ARM, MIPS, PPC, SH4, X86 | PCI | |
| SIS | SIS900 | 1039: 0900 | devn-sis9.so | X86 | PCI | |
| SMC | SMC 8035TX EZ Card 10/100 | N/A | devn-tulip.so | ARM, MIPS, PPC, X86 | CardBus | |
| SMC | 91C90 | N/A | devn-smc9000.so | ARM, SH4, X86 | ISA | |
| SMC | 91C92 | N/A | devn-smc9000.so | ARM, SH4, X86 | ISA | |
| SMC | 91c94 | N/A | devn-smc9000.so | ARM, SH4, X86 | ISA | |
| SMC | 91C96 | N/A | devn-smc9000.so | ARM, SH4, X86 | ISA | |
| SMC | 91C100 | N/A | devn-smc9000.so | ARM, SH4, X86 | ISA | |
| SMC | 91C110 | N/A | devn-smc9000.so | ARM, SH4, X86 | ISA | |
| SMC | 91C111 | N/A | devn-smc9000.so | ARM, SH4, X86 | ISA | |
| SMC | SMC 1211 | N/A | devn-rtl.so | ARM, MIPS, PPC, X86 | PCI | |
| SMC | 1244Tx | N/A | devn-tulip.so | MIPS, PPC, X86 | PCI | |
| SMC | 1255Tx | N/A | devn-tulip.so | MIPS, PPC, X86 | PCI | |
| SMC | SMC 9432 | N/A | devn-epic.so | ARM, MIPS, PPC, X86 | PCI | |
| SMC | SMC EZ Ethernet Adapter | N/A | devn-pegasus.so | ARM, MIPS, PPC, X86 | USB | |
| SMC | LAN83C175 | 10b8: 0006 | devn-epic.so | ARM, PPC, X86 | PCI | |
| SMC | LAN83C170QF | 10b8: 0005 | devn-epic.so | ARM, MIPS, PPC, X86 | PCI | |
| SMC | 8CC795QFP | N/A | devn-wd.so | ARM, MIPS, X86 | ISA | |
| SMC | 2209 | 0x125b: 0x1720 | devn-asix.so | ARM, MIPS, PPC, X86 | USB (released 6.3.0 SP3) | |
| Socket | PCMCIA Low Power Ethernet (LPE) | 0x????: 0x000D | devn-ne2000.so | ARM, MIPS, PPC, SH4, X86 | | |
| Socket | Compact Flash Low Power | 0x????: 0x0075 | devn-ne2000.so | ARM, MIPS, PPC, SH4, X86 | | |

| | | | | | | |
|------------------|-------------------------|------------|-------------------|--------------------------|---------|--|
| | Ethernet (CF + LPE) | | | | | |
| VIA Technologies | VT6305 | 1106: 0926 | devn-ne2000.so | ARM, MIPS, PPC, SH4, X86 | PCI | |
| VIA Technologies | VT86C100 | 1106: 3042 | devn-via-rhine.so | X86 | PCI | |
| VIA Technologies | VT86C100A | 1106: 6100 | devn-via-rhine.so | X86 | PCI | |
| VIA Technologies | VT86C100A | 1106: 3043 | devn-via-rhine.so | X86 | PCI | |
| Winbond | W89C940F | 1050: 0940 | devn-ne2000.so | ARM, MIPS, PPC, SH4, X86 | PCI | |
| Xircom | Cardbus Ethernet 10/100 | 115d: 0003 | devn-tulip.so | PPC, X86 | cardbus | |

Wireless

| Vendor | Model | Vendor:DeviceID | Drivers | Supported CPU | Note | |
|-----------------|----------------------|--|-----------------|----------------|-----------------|--|
| Broadcom | BCM43xx 802.11b/g | 0x14E4; 0x4301, 0x4307, 0x4311, 0x4320, 0x4321, 0x4324, 0x4325 | devn-bcm43xx.so | PPC, SH4, X86 | | |
| D-Link | DWL-520 | 0x1260: 0x3873 | devn-prism.so | ARM, MIPS, X86 | PCI wireless | |
| Intel | 2011/B 802.11B | N/A | devn-prism.so | ARM, MIPS, X86 | PCMCIA Wireless | |
| Netgear | MA401/ MA701 802.11B | N/A | devn-prism.so | ARM, MIPS, X86 | PCMCIA Wireless | |
| Orinoco/ Lucent | 802.11B | N/A | devn-orinoco.so | ARM, X86 | PCMCIA Wireless | |

USB

| Vendor | Model | Vendor:DeviceID | Drivers | Supported CPU | Note | |
|---------|---|-----------------|---------|--------------------------|--|--|
| Generic | USB Open Host Controller Interface | N/A | io-usb | ARM, MIPS, PPC, SH4, X86 | USB host controller. Use -dohci to load the OHCI dll | |
| Generic | USB Universal Host Controller Interface | N/A | io-usb | ARM, MIPS, PPC, SH4, X86 | USB Host controller. Use -duhci to load in the UHCI dll. | |

| | | | | | | |
|---------|---|-----|------------------|--------------------------|---|--|
| Generic | USB Open Host Controllers for Amanda (Shle) | N/A | devu-ohci-amanda | SH4 | | |
| Intel | Enhanced Host Controller Interface | N/A | io-usb | ARM, MIPS, PPC, SH4, X86 | USB 2.0 (High Speed) host controller. Use -dehci option to load EHCI dll. | |
| NEC | 720100 OHCI / EHCI | | io-usb | ARM, MIPS, PPC, SH4, X86 | USB host controller. Use -dohci -dehci to load both the OHCI and EHCI DLLs. | |
| NEC | 720101 OHCI / EHCI | | io-usb | ARM, MIPS, PPC, SH4, X86 | USB host controller. Use -dohci -dehci to load both the OHCI and EHCI DLLs. | |
| OPTi | 82C61 OHCI controller | | io-usb | ARM, MIPS, PPC, SH4, X86 | USB host controller. Use -dohci option to load OHCI DLL. | |
| Philips | ISP1562 OHCI/EHCI controller | | io-usb | ARM, MIPS, PPC, SH4, X86 | USB host controller. Use -dohci -dehci options to load OHCI and EHCI DLLs | |
| VIA | VT83c572 UHCI | | io-usb | X86 | USB host controller. Use -duhci to load the UHCI DLL. | |
| VIA | VT6202 UHCI/EHCI controller | | io-usb | X86 | USB host controller. Use -dehci -duhci to load EHCI and UHCI DLLs. | |